Submit 3 Copies To Appropriate District State of New Mexico .IAN 14 2009 Form C-103 Office Energy, Minerals and Natural Resources May 27, 2004 District I WEELAPINO ESIA 1625 N French Dr., Hobbs, NM 87240 30-015-01660 District II OIL CONSERVATION DIVISION 1301 W Grand Ave , Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S St. Francis Dr , Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Empire Abo Unit 'H' DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 9. OGRID Number 2. Name of Operator 00778 BP America Production Company 10. Pool name or Wildcat 3. Address of Operator P.O. Box 1089 Eunice NM 88231 Empire Abo 4. Well Location 660 line and 660 feet from the feet from the Unit Letter line Township 17S Range 28E **NMPM** County **EDDY** 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3677' GR Pit or Below-grade Tank Application or Closure ___ Depth to Groundwater _ _ Distance from nearest fresh water well _____ Distance from nearest surface water _ Pit Liner Thickness: _ Below-Grade Tank: Volume _____ _bbls; Construction Material 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON **REMEDIAL WORK** ALTERING CASING X **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **TEMPORARILY ABANDON ABANDONMENT MULTIPLE** CASING TEST AND PULL OR ALTER CASING COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/30/08: KILL WELL NU BOP AND RIG UP FLOOR AND TONGS. POH WITH 196 JTS 2 3/8" J-55 TBG. LAST 13 JTS HAD SCALE. MOVE OUT OLD TBG AND MOVE IN 2 3/8" J-55 4.7# WORKSTRING. RIH WITH 4 3/4" BIT. 5.5" SCRAPER ON 187 JT TBG TO 5750'. 12/31/08: KILL WELL WITH 25 BBL BRINE, POH WITH SCRAPER, RIH WITH CIBP TO 5700', SET CIBP PUMP 135 BBL 9.5 SALT GEL MUD, TEST CSG TO 500#. CSG HELD GOOD. 1/2/09: PUMP 25 SX CEMENT PLUG ON CIBP @ 5700'. LD TBG TO GLOREITA 3550' AND PUMP BALANCED 25 SX CEMENT PLUG. LD 9 JTS AND POH WITH 15 STANDS. Continued on page 2. I hereby certify that the information above jet rue and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines ______, a general permit _____or an (attached) alternative OCD-approved plan _____ SIGNATURE Dame barry.price@bp.com E-mail address: Type or print name Baaccepted for record Approved for plugging of well bore only Telephone No. 575-394-1648 Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) For State_Use Only NMOCD which may be found at OCD Web Page under APPROVED BY TITLE Forms, www.cmnrd.state.nm.us/ocd.

Conditions of Approval, if any:

Form C-103 Empire Abo Unit H-25 30-015-01660 Continued from Page 1

1/5/09: POH WITH CIBP SETTING TOOL. RIH WITH PERF SUB AND TAG GLORIETA PLUG 3295'. LD 30 JTS TBG. LD TBG TO 1250'. PUMP 60 SX CEMENT PLUG, LD 21 JTS TBG AND POH.

1/6/09: RIH WITH TBG AND TAGGED @ 648'. LD TBG TO 460' CIRC CEMENT TO SURACE. LD TBG, RIG DOWN TONGS AND FLOOR, ND BOP AND TOP OFF CSG.

1/12/09: DIG OUT AND CUT OFF WELLHEAD, WELD IN PLATE, 1" NIPPLE & VALVE, DRY HOLE MARKER, DIG OUT AND CUT OFF ALL ANCHORS, BACK FILL AND LEVEL LOCATION.