

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

FEB - 4 2009

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-005-61286
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L6773
7. Lease Name or Unit Agreement Name Eastland State
8. Well Number 2
9. OGRID Number 022767
10. Pool name or Wildcat Foor Ranch Pre-Permian
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3836 KB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator The Eastland Oil Company
3. Address of Operator P. O. Box 3488 Midland, TX 79702
4. Well Location Unit Letter <u>K</u> : <u>1980</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section 13 Township 9-S Range 26- E NMPM County Chaves
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3836 KB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Perf: ABO Zone & Treat ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/15/08 - move in & rig up pulling unit. Pull TBG & PKR. Rig up Wireline Unit TIH and set 5 1/2" CIBP @ 5948' w/ 35' Cement on top. Pick up and TIH w/ 5 1/2" CIBP to 5200' & set w/ 35' cement on top. 12/16/08- Perforate 2 holes per ft. @ 4868'-78', 81'-86'. 12/17/8-acidize w/ 1000 gals. 7 1/2 % HCL @ 5 BPM @ 1870 psi. 12/18/08- swab 49 bls load. SI till 12/27/08, rig up, frac w/ 15,000 gals. gel KCL water & 30,000 bls 16/30 sand. 1/15/09-Move in rig up swab unit, swab on well 3 days well kicked off turned down sales line, 1/17/09. 1/30/9 Well is averaging 59MCFD.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed TITLE Agent DATE 2/2/09

Type or print name Travis Reed E-mail address:  PHONE: 432-683-6293

For State Use Only

APPROVED BY:  TITLE  DATE

Conditions of Approval (if any):

Accepted for record  
NMOCD