Form 3160-5 (February 2005)

\$igned

Approved by

(This space for Federal or State Office use)

Conditions of approval, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135 XPIRES: March 31, 2007

EXPIRES: March 31, 2007 FEB 18 700 Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an NM-77046 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. 1a. Type of Well 이 Well Gas Well Other 8 Well Name and No. 2. Name of Operator North Pure Gold 10 Federal 1H **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 3. Address and Telephone No. 30-015-36427 20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611 10. Field and Pool, or Exploratory 4. Location of Well (Report location clearly and in accordance with Federal requirements)* Los Medanos; Delaware 480' FSL 330' FWL M SEC 10 T23S R31E 11. County or Parish State 330' FNL & 660' FWL PP: 480' FSL & 330' FWL NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Deepen Production (Start/Resume) Water Shut-Off Acidize Notice of Intent Alter Casing Fracture Treat Reclamation __ Well Integrity ✓ Subsequent Report **New Construction** ✓ Other Completion Casing Repair Recomplete Change Plans Plug and Abandon Temporarily Abandon Report Final Abandonment Notice Water Disposal Plug Back Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete honzontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has 11/23/08 - 12/19/08 MIRU PU. RU Grey WL. Ran CBL & TOC @ 3150'. RIH w/ 183 jts 2 7/8" J-55 tbg. DO DV Tool @ 5940'. Tag FC @ 12,290'. CHC w/ 2% KCL wtr. Test to 4200#, good. OWU. RIH w/ TCP guns & perf 12,272-74'; 11,687-89'; 11,104-06' & 10,519-21' @ 6 spf, 60 deg phase; total 48 shots. Spot 1700 g 7 1/2% HCL acid. Acidize w/ 2500 g 7 1/2% HCL & 96 BS. RD BJ. Acidize & frac heel section 8179-9936' w/ 301Kg 2800 w/ 12,500# 100 mesh + 371K 20/40 + 111K# 20/40 RC. CHC. MIRU Schlumberger WL. Set CBP and perf: 9934-36'; 9350-52'; 8765-9767' and 8179-81' @ 6 spf: 41 shots. RD MO. RU BJ. RIH w/ pkr & set @ 9950'. Spot 1700g 7 1/2% HCL. Acidize w/ 250 g 7 1/2% HCL and 96 BS. RD BJ. RIse pkr. NU Frac Valve. Frac w/ 301K g Spectra Star 800 w/ 12,500#, 100 mesh white sd, 370,750# 20/40 white sd, 111K# 20/40 SB Excell. FL w/ 184.4 bbbls 10# linear gel. ND Frac Valve & NU BOP. CHC. RD PU and POP. 14. I hereby certify that the foregoing is true and correct

within its jurisdiction.

*See Instruction on Reverse Side

Judy A. Barnett X8699

Regulatory Analyst

FOR RECORDS ONLY

Name

Title

Title

FEB 1 6 2009

BURYAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

Date

Date

1/9/2009

Ulle