Submit 3-Copies To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Re	ources	FEB 2 4 2009	Form C-103 May 27, 2004	
1625 N French Dr., Hobbs, NM 87240 District II OH. CONSCIDENTATION DIV	1	L API NO. 30-015-22913		
1301 W. Grand Ave. Artesia NM 88210 UIL CONSERVATION DI	1.7 1	dicate Type of Lease		
District III 1220 South St. Francis 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505	r.	STATE X FEE		
District IV	6 St	6. State Oil & Gas Lease No.		
1220 S St Francis Dr, Santa Fe, NM 87505	0. 30	ate on & das Lease No	, .	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: Empire Abo Unit 'J'		
1. Type of Well:		8. Well Number		
Oil Well X Gas Well Other		235		
2. Name of Operator	9. OC	GRID Number		
BP America Production Company		00778		
3. Address of Operator		Pool name or Wildcat		
P.O. Box 1089 Eunice NM 88231 4. Well Location	Emp1	re Abo		
Unit Letter G : 1750 feet from the N  Section 6 Township 18S Range  11. Elevation (Show whether DR, R 3672.9' (	28E NM (B, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water	vell Distance fr	om nearest surface water _		
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material				
TEMPORARILY ABANDON		UENT REPORT C  ALTER  PNS.  PLUG  ABANI	ING CASING	
OTHER: Set CIBP to shut off water X OTH	R:		Г	
13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Com or recompletion.	details, and give pertir			
<ol> <li>MIRU PU. Check tbg, csg &amp; surf pipe for pressure - bl TOH w/ rods &amp; pump checking for wear and corrosion. L</li> <li>Monitor well and assure it's stable. ND WH, NU BOP. R</li> <li>RU wireline. Set CIBP at 5977'. RD WL.</li> </ol>	rods as necessar	y. Send pump in for	repairs.	

- 4. TIH w/ prod tbg per Engineering/Production recommendation. Set TAC w/ 15,000# T. ND BOP, NU WH.
- 5. Run pump and rods per Engineering/Production recommendation. Install stuffing box and polished rod.

Seat pump. Check pump action and hang well o 6. RD PU.		coag sox and portened real
I hereby certify that the information above is true and complete to		
grade tank has been/will be constructed or closed according to NMOCD gui	delines, a general permit	or an (attached) alternative OCD-approved plan
SIGNATURE Dany Company	TITLE Area Operati	ons Team Lead DATE 2/24/09
Type or print name Barry C. Price	E-mail address:	barry.price@bp.com Telephone No. 575-394-1648
For State Use Only		
APPROVED BY LAGUE YOUNG	TITLE DISTRICT	11 GOOGEDATE 2/35/C/9
Conditions of Approval, if any:		