

OCD - Artesia

Form 3160-5
(September 2001)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

MARBOB ENERGY CORPORATION

3a. Address

PO BOX 227, ARTESIA, NM 88211-0227

3b. Phone No. (include area code)

(505) 748-3303

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 *[Signature]*
1990 FNL 1295 FEL, SEC. 14-T17S-R29E, UNIT H

RECEIVED

DEC - 5 2003

OCD-ARTESIA

5. Lease Serial No.

NMLC028731B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

M DODD B DEEP FEDERAL #2

9. API Well No.

30-015-31041

10. Field and Pool, or Exploratory Area

GRAYBURG; CISCO

11. County or Parish, State

EDDY CO., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☒ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other _____

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

TESTED THE CISCO ZONE AS FOLLOWS:

10/15/03 - SET CIBP @ 9950'. DUMP BAILER OF CEMENT ON CIBP.

10/16/03 - SPOT 500 GAL 20% NEFE ACID. PERF THE CISCO @ 9068' - 9275' (12 SHOTS). SWAB.

10/20/03 - PERF THE CISCO @ 9015' - 9019' (10 SHOTS). ACIDIZE PERFS (9015' - 9019') W/ 750 GAL 20% NEFE ACID. SWAB.

T/A WELL. EVALUATING ECONOMICS FOR PUMP TEST ON CISCO.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

DIANA J. CANNON

Title PRODUCTION ANALYST

Signature

Date NOVEMBER 10, 2003

ACCEPTED FOR RECORD

DEC - 3 2003

CARLSBAD, NEW MEXICO

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)