

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
N.M. Div-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY DEC 28 2003

3. Address and Telephone No.

P. O. Box 1030
Roswell, New Mexico 88202-1030
OCD-ARTESIA
505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 1980' FEL
Section 21-23S-30E

5. Lease Designation and Serial No.

NM-0543827

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Forty Niner Ridge Unit #2

9. API Well No.

30-015-21175

10. Field and Pool, or Exploratory Area

Forty Niner Ridge Delaware

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice


TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ OTHER Clean-up

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/24/03: RU. TOH w/tbg. Change out split string of tbg. Replace 2-3/8" tbg w/2-7/8" tbg. Clean out w/scraper (7-7/8"). SISD.
10/25/03: TIH w/pkr. Set pkr at 6050'. Swab well. Test okay. FL standing at 2100'. 3% oil cut and producing water. SISD.
10/27/03: TP 300#. Flow well down. Rel pkr. TOH. TIH w/production string. NDBOP. Flange up well head. SISD.
10/28/03: TIH w/pump and rods. Hang well on. W/O electricity. SISD.



14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Production Records Date 12/12/03

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____

Conditions of approval, if any: