

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

JUL 29 2009

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3001522817
3. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-7832
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "E"
8. Well No. 362
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMITS (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED JAN 22 '90 D. C. B. ARTESIA, OFFICE
2. Name of Operator ARCO Oil and Gas Company	
3. Address of Operator Box 1710, Hobbs, New Mexico 88240	
4. Well Location Unit Letter <u>A</u> : <u>1200</u> Feet From The <u>NORTH</u> Line and <u>1200</u> Feet From The <u>EAST</u> Line Section <u>34</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>EDDY</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3675.9 GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN
START WORK ON APPROVAL

Procedures as follows:

1. MIRU DDPV
2. Give NMOCD 24 hr notification of pressure test on csg
3. RIH w/swab to clear tbg
4. Install BOP & POH w/tbg & ACC
5. RIH w/CIBP on tbg
6. Set CIBP @ ± 6115
7. POH w/1 jt
8. Pump 105 BBLS 8.6# brine w/2 gal WT 675/10 BF to establish circulation
9. SI Rams on BOP & press. test to 5-0#. Install chart
10. POH, laying tbg down. Leave 1 jt on flange
11. RDCL. Close all tbg, csg, surface csg valves

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 1-19-90

TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-3551

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 23 1990

MIDLAND
CF - MIDLAND
Artesia
Cogburn

FIELD	OPERATOR	DATE
EMPIRE ABO	ARCO OIL & GAS CO	1-18, 90
LEASE	WELL NO.	LOCATION
EMPIRE ABO UNIT "E"	362	EDDY COUNTY NM UNIT A, SEC 34, T17S, R28E

8 5/8 " CASING SET AT 750 ' WITH 650 SX OF
 _____ CEMENT HOLE SIZE 11 " TOC @ SURF '

5 1/2 " CASING SET AT 6343 ' WITH 1750 SX OF
 _____ CEMENT HOLE SIZE 7 7/8 " TOC @ SURF '

TOTAL DEPTH 6350
 CIBP @ 6200
 PERFS 6124 - 6136