

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT

AUG - 3 2009
 OCD-ARTESIA

FORM APPROVED
 OMB No. 1004-0135
 Expires: January 31, 2004

PM

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mewbourne Oil Company 14744

3a Address

PO Box 5270 Hobbs, NM 88241

3b Phone No. (include area code)

575-393-5905

4. Location of Well (Footage, Sec., T, R., M., or Survey Description)

1650' FSL & 1650' FWL, Unit K, Sec 31-T18S-R30E

File Serial No.

NMNM-27279

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Bradley 31 Federal #2

9. API Well No.

30-015-36619

10. Field and Pool, or Exploratory Area

Turkey Track Grayburg Queen

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other Completion Sundry

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

10/24/08 Perforated Brushy Canyon Delaware @ 4300' - 4427'. 1-2 SPF, 31', .40" EHD.

10/28/08 Frac in 2 stages w/50000 gals 10# brine w/15500# sand.

11/01/08 Run tbg & rods to test Delaware @ 4300' - 4427'.

12/03/08 Delaware noncommercial. POOH w/rods & tbg. Set CIBP @ 4264' w/35' cmt. PBTD @ 4229'.

12/04/08 Perforate Grayburg Queen @ 2528' - 2930'. 2 SPF, 45'. Frac in 2 stages w/1000 gals HCl, 60000 gals WF20 w/80000# 20/40 sand.

12/09/08 Run tbg & rods. Put well on production.

14 I hereby certify that the foregoing is true and correct
 Name (Printed/Typed)

Jackie Lathan

Title Hobbs Regulatory

Signature

Jackie Lathan

Date 07/21/09

ACCEPTED FOR RECORD

JUL 30 2009

/s/ Chris Walls

BUREAU OF LAND MANAGEMENT
 CARLSBAD FIELD OFFICE

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (Signature)

Name
 (Printed/Typed)

Title

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Date

Title 18 U S C Section 1001 and Title 43 U S C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Continued on next page)

MR