

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SEP 22 2009

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.	NMLC068722
6. If Indian, Allottee or Tribe Name	
7. If Unit of CA/Agreement, Name and/or No.	NMNM120425
8. Well Name and No.	Salamander "10" Federal Com #1
9. API Well No.	30-015-35770
10. Field and Pool or Exploratory Area	Grayburg Morrow
11. Country or Parish, State	Eddy County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator BP America Production Company	3a. Address P O. Box 1089 Eunice, New Mexico 88231	3b. Phone No. (include area code) 575 / 394-1648
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650' FNL & 990' FWL Unit Letter "E" Section 10 - T17S - R29E			

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

MIRU PU and ancillary equipment on 8/13/09 to abandon wellbore. Killed well, installed BOP, POH & laid down all production equipment and set abandonment plugs as follows (see attached WB Schematic for additional details):

1. Ran 5 1/2" CIBP on 2 3/8" tubing and set @ 10,505'. Circulated hole clean with freshwater and tested 5 1/2" casing & CIBP to 800 psi, OK. Spotted approximately 100 sx Class "H" onto CIBP. Plug set on 8/19/09 & tagged on 8/20/09 @ 9537'. Morrow - Atoka plug set from 9537' - 10,505'.
2. Set tubing just above bottom plug and circulated hole with 9.0 ppg mud laden fluid.
3. Spotted 25 sx Class "H" from 8214' - 7990' across DV tool @ 8124' on 8/20/09.
4. Spotted 25 sx Class "H" from 7335' - 7110' across top of Wolfcamp on 8/20/09.
5. Spotted 25 sx Class "C" from 6238' - 5975' across top of Abo on 8/20/09.
6. Spotted 25 sx Class "C" from 4014' - 3750' across top of Glorieta on 8/20/09.
7. Spotted 25 sx Class "C" @ 3144' on 8/20/09 and tagged @ 2862' on 8/24/09. Plug set 2862' - 3144', which is across the 9 5/8" intermediate casing shoe @ 3015'.
8. Set bottom of tubing @ 1050' = 119' below top of Yates @ 931', spotted 110 sx Class "C" to surface, laid down tubing and filled casing with cement to compensate for tubing displacement. This plug covers top of Yates @ 931', salt section 350' - 650', 13 5/8" surface casing shoe @ 300' and provides the top plug. This plug was set 8/24/09.
9. RD PU and ancillary equipment on 8/24/09 and cut WH, casings and anchors to 3' below GL and installed regulation Dr. Hole Marker on 8/26/09.

Location will be reclaimed and BLM notified when site is ready for final inspection.

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) M. D. Westmoreland	Title Wells Operation Superintendent
Signature <i>m. d. westmoreland</i>	Date 08/27/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



**Salamander "10" Federal Com #1
Grayburg (Morrow)**

API No. 30 - 015 - 35770
Federal Lease Serial No. NMLC068722

1650' FNL & 990' FWL
Section 10 - T17S - R29E
Eddy County, New Mexico



**Final P&A Status
8/26/09**

