Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-33003
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Name:
PROPOSALS.)  1. Type of Well:			La Huerta 30 Fee Com
Oil Well Gas Well	Other RECEIVED		
2. Name of Operator	• • • • • • • • • • • • • • • • • • • •		8. Well No.
Mewbourne Oil Company  3. Address of Operator	4744 NOV 2.6 7003		#1 9. Pool name or Wildcat
PO Box 5270 Hobbs, NM 88241	OCD-ARTESIA		Burton Flats Morrow
4. Well Location			
Unit Letter J: 2114 feet from the South line and 2487 feet from the East line			
			Total from the
Section 29	Township 21S	Range 27E	NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3134'			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	
	COMPLETION	CEMENT JOB	
OTHER:		OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
11/10/03TD'ed 17 ½" hole @ 404'. Ran 404' 13 3%" 48# H40 ST&C csg. Cement w/250 sks BJ Lite "C" with additives. Mixed @ 12.5			
#/g w/1.98 yd. Tail w/200 sks Class "C" w/2% CaCl2. Mixed @ 14.8 #/g w/1.32 yd. Circ 75 sks cmt to reserve pits. Test BOPE to 1000#, OK. Drilled out with 12 1/4" bit.			
11/15/03Decision made to P&A @ 1115'. Contacted OCD for plugging orders. Plugged well as follows:			
Cmt 1 <sup>st</sup> Plug @ 680' with 145 sks "C" with 3% CaCl2. TIH to tag. Did not tag Cmt 2 <sup>nd</sup> Plug @ 680' with 150 sks "C" with 6% CaCl2. Tagged @ 440'.			
Cmt 3 <sup>rd</sup> Plug @ 440' with 75 sks "C" with 5% CaCl2. Tagged @ 315'.			
Cmt 4 <sup>th</sup> Plug @ 60' with 25 sks "C". Cement to surface.			
11/16/03Install P&A marker. Well plugged @ 10:00 am 11/15/03. Release all rental equipment.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE			
Type or print name NM	oung	Tele	ephone No. 505-393-5905
(This space for State use)			
APPPROVED BY Accepte	d for record - NMOCDTITLE		DATE // /26 /6 3
Conditions of approval, if any:	second - MANACIDITIES		DATE [[] 26 [0 9