Lorin 3160 | 5 (August 2007)

Type of Well

X on Well

Gas Well

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other Instructions on page 2.

Other

RECEIVED
DEC 14 2009
NMOCD ARTESIA
Expues July 31, 2010
Lease Senal No

NMLC028731-A

If Unit of CA. Agreement Name and/or No.

NMNM111789X

If Indian, Allottee, or Tribe Name

Well Name and No

Name of Operator				Dod	ld Federal Unit #110			
Marbob Energy Corporation				9 API Well No				
3a Address		3b Phone No (melu	de area code)]				
PO Box 227		(575) 7	(575) 748-3303	30-015-35139				
Artesia, NM 88211-0227		(373) 748-3303		10 Field and Pool or Exploratory Area				
4 Location of Well (Proviage, Sec. 1), R. M., or Survey Description)					Grbg Jackson; SR-Q-Grbg-SA			
220 POL 1040 PPL C 15 TITC D20F 11.5 D				11 County or Parish State				
330 FSL 1040 FEL, Sec. 15-T17S-R29E, Unit P			Eddy Co., NM_					
12. CHECK APPROL	PRIATE BOX(S) TO INDI	CATE NATURE OF	NOTICE, REPOR	C, OR OTHE	R DATA			
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	Acidize	Deepen	Production (S	tart/Resume)	Water Shut-off			
	Altering Casing	l ractine freat	Reclamation		Well Integrity			
Subsequent Report .	Casing Repair	New Construction	X Recomplete		Other Add Pav			
	Change Plans	Plug and Abandon	Temporardy Abandon					
I mal Abandonment Notice	Convert to Injection	Plug Back	Water Disposa					
I mal Abandonment Notice	Convert to Injection	Plug Back	Water Disposa	ıl				

QCD Archesta

Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markets and sands. Attach the Bond under which the work will performed or provide the Bond No on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Added pay in the Yeso (2) zone as follows:

10/30/09 - MIRU. POOII w/ rods & tbg. Perf the Yeso (2) @ 4592' - 4898' (19 shots).

11/2/09 - Acdz w/ 2000 gal NE Fe 15% HCl

11/5/09 - RHH w/ 153 jts 2 7/8" tbg. Set @ 4924'. RHH w/ pump & rods. Hang well on pump. RDMO.

Producing Interval: Yeso @ 4025' - 4898'

14. Thereby certify that the foregoing is true and correct					
Name (Printed Typed)	1				
	Little				
Quana Driggs	Production Manager				
Signaturd	Date				
THENTHON	1	10	والطر لاالعالى	PLCC	ממנ
THIS SHACE FOR FED	ERAL OR STA			U TUN NEW	MU
11113 SHAPE TOKTED	ENAL ON STA	TE OFFICE O.	Y		
\					
Approved by	Title	į.	000	Date o 2000]
Conditions of approval, if any are attached. Approval of this notice does not warra	nt or	· .	ד טבע	<i>y</i> 3 2009	
certify that the applicant holds legal or equitable title to those rights in the subject lease Office			\$/ Dus	tin Winkler	1 1
	reon		1		
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it actime for any person knowingly and			IRPAROP	M AMPINAMINA OF ME	of the Inited
States any false, fectitious or fraudulent statements or representations as to any matter within its jurisdiction			CARLSE	SAD FIFI D OFFICE	
				7114 141 LV 01 10C	

