Form 3160- 5

UNITED STATES

QCD Artesia

LOKDE GERDATED SUUT

(August 2007)	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				OMB No 1001- 0137				
					MOCD ARTERIA				
CVID				5 Lease Serial No					
SUNDRY NOTICES AND REPORTS ON WELLS					NMLC028731B				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6 If Indian Allottee or Γribe Name				
SUBMIT IN TRIPLICATE - Other Instructions on page 2.					7 If Unit or CA Agreement Name and/or No NMNM111789X				
Type of Well Gas Well Other					8 Well Name and No				
> Name of Operator				- Do	dd Federal Umit #113				
Marbob Energy Corporation					9 API Well No				
3a Address		3b Phone No (include area code)							
PO Box 227		(575) 7	(575) 748-3303		30-015-35247				
Artesia, NM	(3/3)/	10 Field and Pool, or Exploratory Area							
1 Location of Well (Footage, Sec., L. R., M., or Survey Description)				Grbg Jackson; SR-Q-Grbg-SA					
1345 FSL 550 FEL, Sec. 10-T17S-R29E, Unit I					11 County or Parish, State				
					Eddy Co , NM				
12 CHECK APPROF	PRIATE BOX(\$) TO INE	DICATE NATURE OF	NOTICE, REPO	ORT, OR OTHI	'R DATA				
TYPL OF SUBMISSION		ΓΥ							
Notice of Intent	Acidize	Deepen	Production	(Start/ Resume)	Water Shut-off				
	Altering Casing	Fracture Treat	Reclamation		Well Integrity				
Subsequent Report	Casing Repair	New Construction	X Recomplete		Other Add Pay				
	Change Plans	Plug and Abandon	Temporarily	Abandon	· · ·				
1 mal Abandonment Notice	Convert to Injection	Plug Back	Water Dispo	osal	***************************************				
Attach the Bond under which the following completion of the involve	ctionally of recomplete horizon work will performed or provided operations. If the operation Abandonment Notice shall be final inspection.)	tally, give subsurface location the Bond No on file with results in a multiple comple	ons and measured at the BLM/ BIA Re etion or recompletion	nd true vertical dep equited subsequent in a new interval	ik and approximate duration thereonths or pertinent markers and sand- reports shall be filed within 30 day, a Form 3160-4 shall be filed one ten completed, and the operator has				

11/6/09 - MIRU. POOH w/ rods, pump & tbg.

11/9/09 - Perf the Yeso (2) @ 4594' - 4892' (19 shots) Acdz w/ 2000 gal NE Fe 15% HCl

11/12/09 - RIH w/ 152 jts 2 7/8" J55 tbg. Set @ 4925' RIH w/ pump & rods Hang well on pump RDMO. Producing Interval. Yeso @ 4066' - 4892'.

14. Thereby certify that the foregoing is true and correct						
Name (Printed Typed) Wrapa F Briggs	Inte Production Manager					
Signature June Junes	Date			OR RECO)RD	
THIS SPACE FOR FED	OFFICE-U	SE				
Approved by	Title		DEC !	9 ² 11 2009		
Conditions of approval if any are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations the			Winkler			
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it acrim States any false, fictitious or fraudulent statements or representations as to any matter	z v an BUREA CA	IU OF LANI RLSBAD F	D MANAGEME IELD OFFICE	Menev	of the United	
			m	2		