Forn	n	C	-1	03	3
	_	-	~		

	•
Submit 3 Copies To Appropriate District	State of New Mexico
Office	Energy, Minerals and Natural Resources
District I	shorg, remotals and read at resources
1625 N French Dr., Hobbs, NM 87240	
District II	OIL CONCEDUATION DIVISION

	1 1	/\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	/		1111	100
		AN 2 9			ay 27,	2004
	WEHINE	JCB AF	ŢĘŞIA			
	5. Indicat	te Type of	Lease			
	ST	ATE 🗷	FEI	ЕД	]	
	6. State C B-4458	Oil & Gas I	ease No			
) A	7. Lease	Name or U	nit Agre	- emen	t Name	e:
JA	MYCO "BI	B" STATE				
	8. Well N	lumber				·
		010	)			
	9. OGRIE	Number				
	10. Pool	name or V	/ildcat			
	GB JACK	SON (SR-C	N-GR-SA	7)		
d	330	_ feet from	the	WES	<u> </u>	line
5	NMPM		County	·	EDDY	<u> </u>
GR, et	c.)					
ъ.				+		
	tance from n				_	
structio	on Material _	I WAND W.	TUTIN T	,000		

IGO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG RACK TO A PROPOSALS)   MICO "BB" STATE	1220 S St. Francis Dr., Santa Fe, NM 87505  SUNDRY NOTICES AND REPORTS ON WELLS	5. Indicate Type of Lease  STATE  FEE   6. State Oil & Gas Lease No.  B-4458  7. Lease Name or Unit Agreement Name:
Oil Well	DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	MYCO "BB" STATE
2. Name of Operator  10. POOI name or Wildcat  10. Pool name or Wildcat  11. Elevation (Show whether DR RKB, RT, GR, etc.)  23.575' - GR  11. Elevation (Show whether DR, RKB, RT, GR, etc.)  3,575' - GR  12. Check Appropriate Box to Indicate  12. Check Appropriate Box to Indicate  12. Check Appropriate Box to Indicate  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CASING TEST AND   CASING TEST AND    COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CASING TEST AND   CASING TEST AND    OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starring any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  01/25/10: RIH W/ BIT, DC'S X TBG. TO 2,727'; ATTEMPT TO DRILL UP JUNK IN HOLE - UNABLE TO MAKE ADD'L HOLE, 01/26/10: SET 5-1/2" CIEP @ 2,727' (FER R.DADE W/ NOCD); CIEC. WELL W/ BYA MLD; FUMP A 40 SX. CMT. PLUG @ 2,727'; ATTEMPT TO DRILL UP JUNK IN HOLE - UNABLE TO MAKE ADD'L HOLE, 01/26/10: SET 5-1/2" CIEP @ 2,727' (FER R.DADE W/ NOCD); CIEC. WELL W/ BYA MLD; FUMP A 40 SX. CMT. PLUG @ 2,140'-1,940' (CALC.); MIX X FUMP A 25 SX. CMT. PLUG @ 555'-3'; WOX X TG. TO. PLUG @ 660'; MIX X FUMP A 25 SX. CMT. PLUG @ 555'-3'; WOX X TG. TO. PLUG @ 660'; MIX X FUMP A 25 SX. CMT. PLUG @ 555'-3'; DIG CUX X CUT COT OFF WELLHEAD 3' B.G.L.; WELL PLUGGEN X BENEFICED A 1/27/10.  Thereby certify that the information above is Lue and complete to the best of my knowledge and belief. Hurther certify that any pit or belon grade tank has brequired.		
10. Pool name or Wildcat   10. Pool name or Wi	2. Name of Operator	
1.001 FRNNIN ST., SUITE 800, HOUSTON, TEXAS 77002   GB JACKSON (SR-ON-GR-SA)		
4. Well Location   Unit Letter   D   330   feet from the   NORTH   line and   330   feet from the   MEST   line   Section   36   Township   178   Range   29E   NMPM   County   EDDY	· ·	
Unit Letter D : 330 feet from the NCRTH line and 330 feet from the WEST line Section 36 Township 178 Range 29E NMPM County EDDY  11. Elevation (Show whether DR, RKB, RT, GR, etc.)  3,575' - GR  Pitor Below.grade Tank Application or Closure 52  12. Check Appropriate Box to Indicate hobbs: Construction Material * NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING CASING ALT		GB JACKSON (SR-QN-GR-SA)
The continuation   Show whether DR, RKB, RT, GR, etc.  3,575' - GR		330 feet from the WEST line
The continuation   Show whether DR, RKB, RT, GR, etc.  3,575' - GR	Section 36 Township 178 Range 29E	NMPM County EDDY
Pit or Relow-grade Tank Application	<u> </u>	
Distance from nearest fresh water well * Distance from nearest surface water * PR Liner Thickness:		
Pit Liner Thickness:		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT  CASING TEST AND  CEMENT JOB  CE		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  ALTERING CASING  ABANDONMENT  CASING TEST AND  CEMENT JOB  CHENT JOB  C	Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	n Material * NONE WITHIN 1,000'
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  01/25/10: RIH W/ BIT, DC'S X TBG. TO 2,727';ATTEMPT TO DRILL UP JUNK IN HOLE - UNABLE TO MAKE ADD'L HOLE; 01/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOD);CIRC. WELL W/ PXA MUD; FUMP A 40 SX. CMT. PLUG @ 2,727'; MIX X PUMP A 25 SX. CMT. PLUG @ 2,140'-1,940' (CALC.); MIX X PUMP A 25 SX. CMT. PLUG @ 974'; WCC X TAG CMT. PLUG @ 942'.  01/27/10: MIX X PUMP A 25 SX. CMT. PLUG @ 942' (PER P.HOPKINS W/ NMOD); WCC X TAG CMT. PLUG @ 942'.  01/27/10: MIX X PUMP A 25 SX. CMT. PLUG @ 942' (PER P.HOPKINS W/ NMOD); WCC X TAG CMT. PLUG @ 680'; MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG @ 535'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELL PLUGGED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belograde tank has been with the constructed or losed according to MNOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan SIGNATURE  TITLE AGENT DATE 01/28/10  E-mail address: devler@mllagro-res.com  Telephone No. (432) 687-303	NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI  PULL OR ALTER CASING MULTIPLE CASING TEST AND	SEQUENT REPORT OF:  ALTERING CASING  NG OPNS. PLUG AND
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  01/25/10: RIH W/ BIT, DC'S X TEG. TO 2,727'; ATTEMPT TO DRILL UP JUNK IN HOLE - UNABLE TO MAKE ADD'L HOLE; 01/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOOD); CIRC. WELL W/ PXA MUD; PUMP A 40 SX. CMT. PLUG @ 2,727'; MIX X PUMP A 25 SX. CMT. PLUG @ 2,140'-1,940' (CALC.); MIX X PUMP A 25 SX. CMT. PLUG @ 974'; WCC X TAG CMT. PLUG @ 942'.  01/27/10: MIX X PUMP A 25 SX. CMT. PLUG @ 942' (PER P.HOPKINS W/ NMOOD); WCC X TAG CMT. PLUG @ 680'; MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG @ 535'-3'; DIG CUT X CUT OFF WEILHEAD 3' B.G.L.; WELD ON 1/2" STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARKER.  WELL PLUGGED X ARANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belograde tank has been with be constructed or losed according to MTOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan SIGNATURE  E-mail address:  Type or print name DAVID A. EYLER  TITLE  AGENT  DATE  01/28/10	COMPLETION CEMENT JOB	
01/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOCD); CIRC. WEIL W/ PXA MUD; PUMP A 40 SX. CMT. PIUG @ 2,727'; MIX X PUMP A 25 SX. CMT. PIUG @ 2,140'-1,940' (CALC.); MIX X PUMP A 25 SX. CMT. PIUG @ 974'; WCC X TAG CMT. PIUG @ 942'.  01/27/10: MIX X PUMP A 25 SX. CMT. PIUG @ 942' (PER P.HOPKINS W/ NMOCD); WCC X TAG CMT. PIUG @ 680';  MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PIUG @ 535'-3'; DIG OUT X CUT OFF WEILHEAD 3' B.G.L.;  WELL PLUCCED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belograde tank has been with be constructed or closed a cording to MTOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan SIGNATURE  TITLE  AGENT DATE  01/28/10  E-mail address:  Ceyler@mllagro-res.com  Telephone No. (432) 687-303.		
MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG @ 535'-3'; DIG CUT X CUT OFF WELLHEAD 3' B.G.L.;  WELD ON 1/2" STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARKER.  WELL PLUGGED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belongrade tank has been with be constructed or closed according to MVOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan SIGNATURE  TITLE AGENT DATE 01/28/10  E-mail address: devler@mllagro-res.com  Type or print name DAVID A. EYLER	OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  The proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below grade tank has been will be constructed or closed according to MYOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan SIGNATURE  TITLE AGENT DATE 01/28/10  E-mail address: deyler@mlagro-res.com  Type or print name DAVID A. EYLER  Telephone No. (432) 687-303.	OTHER:  OTHER:	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE;  PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WOC X TAG CMT. PLUG @ 942'.
grade tank has been will be constructed on closed according to MNOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan SIGNATURE  TITLE AGENT DATE 01/28/10  E-mail address: deyler@mlagro-res.com  Type or print name DAVID A. EYLER  Telephone No. (432) 687-303.	OTHER:  OTHERE:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE;  PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WOC X TAG CMT. PLUG @ 942'. ); WOC X TAG CMT. PLUG @ 680'; G OUT X CUT OFF WELLHEAD 3' B.G.L.;
Type or print name DAVID A. EYLER  E-mail address: deyler@mllagro-res.com Telephone No. (432) 687-303	OTHER:  OTHER:	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE;  PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WOC X TAG CMT. PLUG @ 942'. ); WOC X TAG CMT. PLUG @ 680'; G OUT X CUT OFF WELLHEAD 3' B.G.L.;
Type or print name DAVID A. EYLER  Telephone No. (432) 687–303.	OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  01/25/10: RIH W/ BIT, DC'S X TBG. TO 2,727'; ATTEMPT TO DRILL UP JUNK 01/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOCD); CIRC. WELL W/ @ 2,727'; MIX X PUMP A 25 SX. CMT. PLUG @ 2,140'-1,940' (CAL @ 1,430'-1,230' (CALC.); MIX X PUMP A 25 SX. CMT. PLUG @ 974 01/27/10: MIX X PUMP A 25 SX. CMT. PLUG @ 942' (PER P.HOPKINS W/ NMOCD MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG @ 535'-3'; DI WELD CN 1/2" STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARK WELL PLUCCED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to MITOCD guidelines X, a general permit	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE; PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WCC X TAG CMT. PLUG @ 942'. ); WCC X TAG CMT. PLUG @ 680'; G OUT X CUT OFF WELLHEAD 3' B.G.L.; ER.  ge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan—
	OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  01/25/10: RIH W/ BIT, DC'S X TBG. TO 2,727';ATTEMPT TO DRILL UP JUNK 01/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOOD);CIRC. WELL W/ @ 2,727'; MIX X PUMP A 25 SX. CMT. PIUG @ 2,140'-1,940' (CAL @ 1,430'-1,230' (CALC.); MIX X PUMP A 25 SX. CMT. PIUG @ 974 01/27/10: MIX X PUMP A 25 SX. CMT. PIUG @ 942' (PER P.HOPKINS W/ NMOOD MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PIUG @ 535'-3'; DI WELD ON 1/2" STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARK WELL PLUCCED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledgrade tank has been with the constructed or woosed according to MYTOCD guidelines X, a general permit SIGNATURE	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE; PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WOC X TAG CMT. PLUG @ 942'. ); WOC X TAG CMT. PLUG @ 680'; G OUT X CUT OFF WELLHEAD 3' B.G.L.; ER.  ge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan—
APPROVED BY TITLE which may be found as OCD Web Proceedings of Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) ATE 2/1/20	OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  O1/25/10: RIH W/ BIT, DC'S X TBG. TO 2,727';ATTEMPT TO DRILL UP JUNK O1/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOOD);CIRC. WELL W/ @ 2,727'; MIX X PUMP A 25 SX. CMT. PLUG @ 2,140'-1,940' (CAL @ 1,430'-1,230' (CALC.); MIX X PUMP A 25 SX. CMT. PLUG @ 974 O1/27/10: MIX X PUMP A 25 SX. CMT. PLUG @ 942' (PER P.HOPKINS W/ NMOOD MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG @ 535'-3'; DI WELD CN 1/2" STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARK WELL PLUGGED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowledgrade tank has been with the constructed or wosed according to MITOCD guidelines X, a general permit SIGNATURE  TITLE  E-mail address:  Type or print name DAVID A. EYLER	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE; PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WCC X TAG CMT. PLUG @ 942'. ); WCC X TAG CMT. PLUG @ 680'; G OUT X CUT OFF WELLHEAD 3' B.G.L.; ER.  ge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan  ENT DATE 01/28/10  Leyler@m.lagro-res.com  Telephone No. (432) 687-3033
APPROVED BY TITLE which may be found at OCD Web Page under Conditions of Approval, if any:	OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  01/25/10: RIH W/ BIT, DC'S X TEG. TO 2,727';ATTEMPT TO DRILL UP JUNK 01/26/10: SET 5-1/2" CIBP @ 2,727' (PER R.DADE W/ NMOCD);CIRC. WELL W/ @ 2,727'; MIX X PUMP A 25 SX. CMT. PLUG @ 2,140'-1,940' (CAL. @ 1,430'-1,230' (CALC.); MIX X PUMP A 25 SX. CMT. PLUG @ 974 01/27/10: MIX X PUMP A 25 SX. CMT. PLUG @ 942' (PER P.HOPKINS W/ NMOCD MIX X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG @ 535'-3'; DI WELD CN 1/2" STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARK WELL PLUGGED X ABANDONED 01/27/10.  1 hereby certify that the information above is true and complete to the best of my knowled grade tank has been with the constructed or closed according to MITOCD guidelines X, a general permit [SIGNATURE TITLE AGE E-mail address:  Type or print name DAVID A. EYLER  Approved for pluggit Liability under bond of Cald's Subsequence.	wellbore diagram of proposed completion  IN HOLE - UNABLE TO MAKE ADD'L HOLE; PXA MUD; PUMP A 40 SX. CMT. PLUG C.); MIX X PUMP A 25 SX. CMT. PLUG '; WOC X TAG CMT. PLUG @ 942'. ); WOC X TAG CMT. PLUG @ 680'; G CUT X CUT OFF WELLHEAD 3' B.G.L.; ER.  ge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan  ENT DATE 01/28/10  Reyler@milagro-res.com  Telephone No. (432) 687-3033  g of well bore only. is retained pending receipt is Report of Well Planator.