
p.4

Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
District   1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO.
District II	OIL CONSERVATION DIVISION	30-015-26727
1301 W. Grand Ave., Artesia, NM 88210 District [1]	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE STATE FEE  6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505		V. Date On & Gus Ecuse 140.
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name HANNAFIN STATE # 1
PROPOSALS) 1. Type of Well: Oil Well  Gas Well  Other		8. Well Number #1
2. Name of Operator		9. OGRID Number
NEW MEXICO OCD FOR PRONGI	HORN	10. Pool name or Wildcat
3. Address of Operator		10. Poor name or windcat
4. Well Location		
Unit Letter: L : 33	0feet from theW line and1650	feet from theSline
		MPM EDDY County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	)
Pit or Below-grade Tank Application _ or (	Closure 🗌	
	Distance from nearest fresh water well Dis	tance from nearest surface water
Pit Liner Thickness: mil		onstruction Material_
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
		•
NOTICE OF INT	PLUG AND ABANDON 🛛 REMEDIAL WOR	SEQUENT REPORT OF:  RK
		ILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	T JOB
OTHER:	□ OTHER:	
13. Describe proposed or complet	ted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work or recompletion.	s). SEE RULE 1103. For Multiple Completions: A	ttach wellbore diagram of proposed completion
1. RIH AND SET 4 ½" CIBP @	9 1938' – TOP WITH 25 SACKS – CIRCULATE PI	LUGGING MUD
2. PERF AND SPOT 35 SACKS @ 1420' – TAG		
3. PERF AND SPOT 35 SACKS @ 810` – TAG 4. PERF AND SPOT 35 SACKS @ 300` – TAG		
5. PERF AND CIRCULATE 25 SACKS FROM 60' TO SURFACE		
	KER AND CLEAN UP LOCATION	
		Notify OCD 24 hrs. prior
		To any work done.
		io dily work done.
STEEL PITS WILL BE USED FOR T	HIS PROCEDURE	
I hereby certify that the information ab	ove is true and complete to the best of my knowledge	e and helief I further cortify that any sites below
grade tank has been/will be constructed or eld	sed according to NMOCD guidelines , a general permit	or an (attached) alternative OCD-approved plan .
2/11/2 11/1	/ TITLE agent for ocd	
SIGNATURE AND STATE	TILE agent for occ	DATE_4/17/10
Type or print name	E-mail address:	Telephone No.
For State Use Only	·D	
APPROVED BY:	TITLE_	DATE4/15/200

Approval Granied provining with DATE \$15/200 is complete by \$129/200

Well Name API #30-015-26727 HANNIFIN ST. #1

4/19/2010



15 SX @ 60' TO SURFACE'

878"CSG

TOC @ 78' ant 10 Suiser 6/4/1. PM

35 SX @ 300'

Surface Casing @ 250'

. TSOH 335'

35 SACKS @ 810" B Sa IT

41/2" csc. Toc e 320' T.S

35 SX @ 1420'

CIBP: @ 1938' W/ 25 SX ON TOP

PERFS: @ 1988' 4 1/2" CASING @ 2260'

Hole TD: 2112'

Company Name:

OCD FOR PRONGHORN