

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Hanson Operating Company, Inc.

3. Address of Operator

PO Box 1515, Roswell, NM, 88202-1515

4. Well Location

Unit Letter I : 2310 feet from the South line and 330 feet from the East line
Section 12 Township 9-S Range 29-E NMPM County Chaves

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4082', GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

04/19/10 MIRU rig and cementing equipment. Unseat pump and lay down pump and rods. SDFN.

04/21/10 POH w/ tbg. RIH w/ CIBP and set @ 3150'. Circulate hole w/ mud laden fluid. Spot 25 sx class C cement on top of plug. POH w/ tbg. Perf casing @ 945'. Set Packer @ 650'. Break circulation and Sqz. 50 sx class C cement. SDFN.

04/22/10 Tag plug @ 718'. POH w. tbg. Perf. casing @ 400'. Sqz. 100 sx class C cement and circulate to surface. POH. Top off surface w/ 15 sx cement. rig down Move off.

04/23/10 Cut off well head and weld on Dry Hole Marker. clean loc & move off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Carol J. Smith TITLE Production Analyst DATE 6/9/2010

Type or print name Carol J. Smith

E-mail address: hanson@dfn.com

Telephone No. 575-622-7330

For State Use Only

APPROVED BY [Signature] TITLE _____

Conditions of Approval (if any):

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms provided by Forms On A-Disk (214)
Forms: www.enr.state.nm.us/oed

DATE 6/14/2010

340-9429 · FormsOnADisk.com