

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-24653
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. NM01119
7. Lease Name or Unit Agreement Name Avalon (Delaware) Unit
8. Well Number 210
9. OGRID Number 007673
10. Pool name or Wildcat Avalon Delaware 3715

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Exxon Mobil Corporation

3. Address of Operator
P O Box 4358; CORP, MI-203; Houston, TX. 77210

4. Well Location

Unit Letter I : 990 feet from the N line and 990 feet from the W line
Section 30 Township 20S Range 28E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3295 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

P&A permit expired 07/27/2010.

Operator requires more time and respectfully requests administrative approval to P&A per attachments.

attachments:
procedure
schematics

Final P/A Extension

Approval Granted providing work
is complete by 9/6/2010

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy L. Springfield TITLE Regulatory Specialist DATE 07/01/2010

Type or print name Roy L. Springfield E-mail address: roy.l.springfield@exxonmobil.com PHONE: 281-654-1932
For State Use Only

APPROVED BY: [Signature] TITLE _____ DATE 7/6/2010
Conditions of Approval (if any):

ADU 210 Plugging Procedure:

1. Check wellhead PSI and flow down accordingly.
2. MIRU plugging equipment.
3. ND wellhead NU BOP.
4. POH with kill string.
5. TIH with work-string and tag existing CIBP @ 2,500'.
6. Circulate well with plugging mud. 100 BBLs 50 sks.

⑦ Spot 25 sks of C cement @ 2,500'-~~2,400'~~ Tag plug.

2322'

* 8. RU wireline, test per regulations, and perforate at 700'. RIH to 700'. Squeeze 55 sks of C cement 700'-400'.

9. POH with tubing.

10. RU wireline, test per regulations, perforate @ 200'.

11. Establish circulation out 8 5/8" annulus. Circulate 100 sks of C cement down 5 1/2" up 8 5/8" annulus to surface.

12. ND BOP

13. Mechanical cut 5 1/2" casing 5' BGL.

14. ND BOP & wellhead. Remove 5 1/2" casing stub 5' BGL.


15. Mechanical cut 8 5/8" casing 3' BGL.

16. Rig down plugging equipment.

17. Cut off wellhead and anchors 3' BGL. Cap well. Install dry hole marker.

17. * 8 5/8" csg shoe @ 2372' 100' cement plug 2422'-2322' woc tag
2500'-2322'

ADU 210 Current Wellbore Schematic



ADU 210 Proposed Wellbore Schematic

