RN

Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District 1 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-015-21064 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE \[ \] FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Maude Rickman DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH **6** 2010 PROPOSALS.) 8. Well No. 1 1. Type of Well: Oil Well ☐ Gas Well ☒ Other 9. OGRID Number NMOCD ARTESIA Name of Operator State of New Mexico (formerly Willow Creek Resources, Inc.) Address of Operator 10. Pool name or Wildcat 1301 West Grand Ave; Artesia, NM 88210 Cass Draw - Wofcamp 4. Well Location Unit Letter I : 2203.7 feet from the South line and 839.7 feet from the West line Section 3 Township 23-S Range 27-E **NMPM** County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3113 Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK □ ALTERING CASING □ COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB **CHANGE PLANS TEMPORARILY ABANDON PULL OR ALTER CASING** MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 06/21/10 MIRU cementing equipment and rig. rigged up SDFN. 06/22/10 NU BOP. Kill Well, POH with 2 3/8 buttress tbg. Take off SN. RIH w/ tbg. SDFN. 06/23/10 Finish running tbg. in hole. Tagged plug @ 9660'. Pumped 80 bbls of mud laiden fluid. POH to 9000', Pumped 50 bbls of mud laiden fluid. Spot 25 sx cement. POH to 6570'. Pumped 50 bbls of mud laiden fluid. Spot 25 sx cement. POH to 5621'. Pumped 40 bbls of mud laiden fluid. Spot 60 sx. cement. Pull out of cement WOC SDFN. 06/24/10 Tagged plug @ 5369'. POH to 2200'. Load hole and spot 50 sx. cement. POH to 405'. Spot 50 sx cement. Pull out of cement WOC. Tagged plug @ 300'. POH w/ tbg. ND BOP. RIH to 60'. Circulated 25 sx cement to surface. Rigged down clean location and moved off. 06/28/10 Moved in back hoe and welder. Dug out cellar, cut off well head, weld on Dry Hole Marker. Back fill cellar, Cut off dead men. clean location and move off. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . SIGNATURE /2 TITLE Agent DATE 6-30-10 E-mail address: beame bem and Assa diotestionen No. 432.5-80-7141 Type or print name Ben Mou For State Use Only TITLE APPROVED BY

Conditions of Approval (if any):