Submit I Copy To Appropriate District Office	State of New Mexico				Form C-103
District I	Energy, Minerals and Natural Resources			October 13, 2009	
1625 N. French Dr., Hobbs, NM 88240	625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
1301 W Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION			30-015-01289		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Typ	
1000 Rio Brazos Rd , Aztec, NM 87410			STATE	FEE _	
District IV 1220 S. St. Francis Dr., Santa Fe, NM				6. State Oil & C	Jas Lease No.
87505					
SUNDRY NOTICES AND REPORTS ON WELLS					or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORME			UG BACK TO A	EAST RED LA	KE UNIT TRACT 1
PROPOSALS.)	RECEIVED				
1. Type of Well: Oil Well	ILCLIALD		8. Well Numbe	r 002	
2. Name of Operator	.1[1]	16 2010	9. OGRID Nun	nber	
TANDEM ENERGY CORPORAT	002	10 2010	10068		
3. Address of Operator		NMOCD ARTESIA		10. Pool name	or Wildcat
11490 WESTHEIMER RD, STE. 1	7077	RED LAKE; QUEEN-GRAYBURG, EAST			
4. Well Location					
Unit Letter L: 1980 feet from the S line and 660 feet from the W line					
Section 36 Township 16S Range 28E NMPM EDDY County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
11. Dievation (Snow whether DR, RRD, RT, GR, etc.)					
[20] [20] [20] [20] [20] [20] [20] [20]					
12 Chaole A	appropriate Box to I	Indianta N	Intura of Motica	Papart or Otha	or Dota
12: Check A	'bbrobriate pox to i	illuicate iv	iature of Notice	, Report of Othe	n Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR					
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR				=	P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
DOWNHOLE COMMINGLE	== 00 =				
OTHER:			OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
1. TAG CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TOP 2. SPOT 25 SACKS @ 1150' – TAG					
4 SPOT 25 SACKS FROM 60' TO SURFACE					
5. INSTALL PA MARKER – CLEAN LOCATION					
3. SPOT 25 SACKS @ 400' – TAG 4 SPOT 25 SACKS FROM 60' TO SURFACE 5. INSTALL PA MARKER – CLEAN LOCATION					
Months and the second of the s					
					74 243
					On On
	•				10 W
			Γ-		
Spud Date:	Rig	Release Da	ate:		
L					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
	too vo to trao and comp.			Se and over	
sel D s.	<i>i</i> 1				
SIGNATURE Man OH			-		
TITLEAGENT	Γ	DATE	_7/15/10		
	SKINS E-mail a	ddress:		PHONI	E:575-726-1366
For State Use Only	^				
the Lite				, 1.	
APPROVED BY:	TCC TIT	LEA	oproval Granted pr	oviding WOTK D	ATE // 17/20/0
APPROVED BY: TITLE Approval Granted providing work DATE 7/19/2010 is complete by 10/19/2010					
		R	יייייייייייייייייייייייייייייייייייייי	/	

Well Name API #30-015-01289 EAST RED LAKE UNIT TRACT 1 # 2

25 SX @ 400'

25 SX @ 60' TO SURFACE'

Surface Casing @ 350'

25 SACKS @ 1150'

25 SX TOP OF CIBP @ 1617'

Company Name: TANDEM