Form 3160-5 (August 2007)

ÚNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RESPANSES	665	Appela a
------------------	------------	----------

FORM APPROVED OMB No 1004-0137

Expires July 31, 2010

5. Lease Serial No. LC029419A

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name				
- SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well		*** * * * ****				071030X			
Oil Well Gas Well Other					8. Well Name and No. Skelly Unit #116				
2. Name of Operator Sandridge Expl and Prod. LLC					9. API Well No. 30-015-21090				
3a. Address 3b. Phone No. (incl				ode) 10. F	ield and Pool or I	Explorator	y Area		
2130 W. Bender Hobbs, NM 88240	39		Grayburg Jac	ckson; SF	R-Q-SA				
4. Location of Well (Footage, Sec., T.,	11. C	11. Country or Parish, State							
Sec. 22 T17S, R31 E 1330' FSL 130' FV	VL.				Eddy				
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO IND	ICATE NATUR	E OF NOTICE, RE	PORT OR OTH	ER DATA			
TYPE OF SUBMISSION		· · · · · · · · · · · · · · · · · · ·	TY	PE OF ACTION		***************************************		***************************************	
	Acidize	Deep	en	Production	(Start/Resume)	Water Shut-Off			
Notice of Intent	Alter Casing	= :	ure Treat	Reclamation	· · · · · · · ·				
[C] S. Love and Provent	Casing Repair	☐ New	Construction	Recomplete		Ot	her		
✓ Subsequent Report	Change Plans	Plug	and Abandon	Temporarily	mporarily Abandon				
Final Abandonment Notice	Convert to Injection		Back	Water Disp	osal				
determined that the site is ready for 8-10-10 MIRU PU. Hot wtr annulus 8-11-10 Unseated pump. POH LD 91 jts tbg. 8-12-10 Finished RIH w/bit, tagged hydrotested tbg. BIH to 6000psi. P @3039'. 8-13-10 Acidize perfs 3156-3543' w PU & RIH w/ RBP & pkr, set RBP @ solvent w/500# RS. in 2 stages. 8-14-10 Release pkr, latched onto I @1700' 8-16-10 Made 39 swab runs, Rec. 20 WH. PU & RIH w/pump & rods. Hu Return well to production.	s & left pumping. pump. POH w/ 2 7/8" not @3595'. Drilled 3595-36i U &RIH w/RBP & ArrowSo u/2000 gals 15% Anti-slud 03000'. Set pkr @2135'. RBP @3000 and released	00'. Started dr et pkr. RD test ge NEFE w/H2 Acidize perfs 2 . POH LD RBI	illing metal & quers. Tagged w. S scavenger & 238-2363' w/20	uit making hole. (/RBP @3212'. P 2% mutal solveni 00 gals 15% Anti set @2135'. RU	Circ. hole clean. OH w/pkr & LD : w/500# RS in : -sludge NEFE v swab unit, mad	POH LE RBP. RII 2 stages. v/H2S sca le 31 runs tbg. ND	DC's & bit. Fellowing wenger & 2% Rec74 bbls Catch pan & B	RU testers, swinging r & POH. mutal s. FFL	
		100				S	EP 23 20	010	
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Colleen Robinson			Title SR. Pro		NMC	CD ART	ESIA		
Signature Que Tobir	~		Date 08/23/20		ACCE	טובט	FOR DI	ECURD	
	THIS SPACE	FOR FEDE	RAL OR ST	ATE OFFICE	USE	1 L D	1 011 111		
Approved by							47 - 1		

(Instructions on page 2)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 18 U S C. Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction Accepted for record

Title

Da6FP 2 0 2019

CARLSBAD FIFLD OFFICE

ment or agency of the Whited States lany false,