Submit 1 Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 8 PECEIVED District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa PMOCD ARTESIA 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM.C-101) FOR SUCH	Form C-103 October 13, 2009 WELL API NO. 30-015-32522 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. V-1673 7. Lease Name or Unit Agreement Name Lost Tank AIS State
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other REVISED 2. Name of Operator Yates Petroleum Corporation 3. Address of Operator 105 South Fourth Street, Artesia, NM 88210	8. Well Number 10 9. OGRID Number 025575 10. Pool name or Wildcat Lost Tank; Delaware
4. Well Location Unit Letter L: 1650 feet from the South line and 990 feet from the West line Section 36 Township 218 Range 31E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3549'GR	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of the proposed completion or recompletion.	
OTHER: OTHER: OTHER: OTHER: Works 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including disputed derection of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
Yates Petroleum Corporation plans to plug and abandon this well as follows: 1. MIRU WSU. Rig up any safety equipment as needed. No casing recovery will be attempted. TOH with tubing and production equipment. 2. Set a CIBP at 6730' with 35' cement on top. This will put a plug over open Delaware perforations. 3. Spot a 390 sx Class "C" cement plug from 4420'-532'. This will put a solid, continous plug across the top of the Delaware, across intermediate casing shoe, across DV tool and across the salt section. To ensure a good and safe job we will have to use multiple plugs and plan to spot a 100 sx cement plug at the time. WOC and tag. 4. Spot a 15 sx, 60' surface plug. 5. Remove all surface equipment and weld dry hole marker and clean location as per regulations.	
Due to the volume of wells we currently have plans to plug, both State/Fee and Federal, Yates Petroleum respectfully requests a time frame of 1 year to have commenced plugging operations and for this notice of intent to be in affect	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	
Type or print name Tina Huerta E-mail address: tinah@yatespetroleum.com PHONE: 575-748-4168 For State Use Only Approval Granted providing work	
APPROVED BY: Approval Granted providing Conditions of Approval (if any): Approval Granted providing is complete by 1/1/2/	DATE 1//17/2010



