Form 3160-5 (Sei Juary 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APROVED
OMB NO. 1004-0135
EXPIRES: March 31, 200

BUREAU OF LAND MANAGEMENT	EXPIRES: March 31, 2007			
SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Serial I	5. Lease Serial No.		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals	NMNM-99147 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE	1			
000//// IIV III 210/// 2	7. Unit or CA Agreement Name and No.			
1a. Type of Well 🗌 Oil Well 🔲 Gas Well 🔲 Other	0.141.01			
	8 Well Name and No.			
2. Name of Operator	Slider 8 Federal 1H			
DEVON ENERGY PRODUCTION COMPANY, LP	9. API Well No.			
3. Address and Telephone No.	30-015-38242			
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611	10. Field and Pool, or Exploratory			
Location of Well (Report location clearly and in accordance with Federal requirements)* J SEC 8 T25S R29E	Willowlake; Bone Spring, Southeast 11. County or Parish State			
BHL: 2220' FSL & 330' FWL	Eddy	NM		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOIL TYPE OS SUBMISSION TYPE OF ACTION		ATA		
		☐ Water Shut	Off	
✓ Notice of Intent	on (Start/Resume)	Well Integr		
Subsequent Report Casing Repair New Construction Recompl		☑ Other Asht		
Change Plans Plug and Abandon Tempora	rily Abandon			
Final Abandonment Notice Convert to Injection Plug Back Water Di T3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. A Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation is the propertion of the involved operations of the involved operations of the involved operations. If the operation is the properties of the following characteristic operations of the involved operations of the involved operations of the involved operations. If the operation is the properties of the following characteristic operations of the involved operations of the involved operations of the operation of the involved operations of the operation of the involved operations of the involved operations of the operation of the involved operations of the involved operations of the operation operation operations of the involved operation of the involved operation of the involved operations of the involved operation operatio	ation results in a multiple anges: I.	e completion or recompleti	on in a new interval	
Another rig will drill the remainder of the wellbore. The reasons for using the smaller rig economics.	to set surface a	are: rig availabili	ity and	
The BLM will be contacted 24 hours prior to commencing drilling operations. The surface surface as per the approved APD. The well will be secured with a cap welded onto the sullocation to drill the remainder of the wellbore within 60 days after the Ashton rig has left	rface casing. A	nother rig will b	oe on	
SEE ATTACHED FOR	RECEIVED			
CONDITIONS OF APPROVAL NOV 1 9 2010			2010	
COLADITIO14D OF 1ST F160 A151	· .		TEOLA	
14. I hereby certify that the foregoing is true and correct		NMOCD AF	TESIAT	
Signed Name Judy A. Barnett X8699 Title Regulatory Ánalyst	ABRRO	VE _{1/8/2010}		
(This space for Federal or State Office use)				
	HOV 17	2010		
Approved by Title Conditions of approval, if any:		LUIU	 	

*See Instruction on Reverse Side

within its jurisdiction.



95 FEET

Cotton Draw Unit 134H Devon Energy Production Company, LP November 17, 2010 Conditions of Approval

- 1. Notify the BLM when removing the Ashton Oilfield Services Rig.
- 2. Notify the BLM when moving in the H&P Flex Rig. Rig to be moved in within 60 days of notification that Ashton Oilfield Services Rig has left the location. Failure to notify or have rig on location within 60 days will result in an Incident of Non-Compliance.
- 3. Once the H&P Flex Rig is on location, it shall not be removed from over the hole without prior approval unless the production casing has been run and cemented or the well has been properly plugged. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
- 4. The CIT for the surface casing shall be performed and results recorded on subsequent sundry pressure to be 1200 psi.

WWI 111710