District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-

APPLICATION FOR PERMIT TO DRILL

MARBOB ENERG	Operator Name and Address MARBOB ENERGY CORP				
PO Box 227 Artesia, NM 8821	PO Box 227 Artesia, NM 88211-0227				
Property Code	Property Name	Well No.			
33449	TWIX FEE COM	001			

Surface Location

UL or	ot Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
Н	4	22S	27E	Н	1980	N	990	E	Eddy

Proposed Pools

CARLSBAD; MORROW, SOUTH (PRO GAS) 73960

Work Type New Well	Well Type GAS	Cable/Rotary	Lease Type Private	Ground Level Elevation 3101
Multiple N	Proposed Depth 12000	Formation Morrow	Contractor	Spud Date 03/01/2004

Proposed Casing and Cement Program

Туре	Hole Size	Casing Size	Casing Weight/ft	Setting Depth	Sacks of Cement	Estimated TOC
Surf	17.5	13.375	48	375	300	0
Int1	12.25	9.625	36	1700	900	0
Int2	8.75	7	23	9000	1600	1450
Prod	6.125	4.5	11.6	12000	350	8750

Casing/Cement Program: Additional Comments

13 3/8 and 9 5/8 casing will have cement circulated to surface. 7 inch casing will be cemented with sufficient cement to tie back in to 9 5/8 casing. 4 1/2 casing will be cemented to tie back in to 7 inch casing.

Proposed Blowout Prevention Program

with the second	the contract commence that is also a supplied that the contract contract contracts and the contract co		
Туре	Working Pressure	Test Pressure	Manufacturer
Double Ram	5000	5000	Cameron

I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Electronically Signed By: Diana Cannon

Title: Production Analyst

Date: 02/17/2004

Phone: 505-748-3303

OIL CONSERVATION DIVISION

Electronically Approved By: Bryan Arrant

Title: Geologist

Approval Date: 02/18/2004 Expiration Date: 02/18/2005

Conditions of Approval:

No Conditions

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number 30-015-33246	Pool Name CARLSBAD;MORROW, SOUTH (PRO GAS)	Pool Code 73960	
Property Code 33449	Property Name TWIX FEE COM	Well No.	
OGRID No. 14049	Operator Name MARBOB ENERGY CORP	Elevation 3101	

Surface And Bottom Hole Location

IL or Lot Section H 4	Township 22S	Range 27E	Lot Idn H	Feet From 1980	N/S Line N	Feet From 990	E/W Line E	County Eddy	
Dedicated Acres 319.84	Joint or	Infill	Consoli	dation Code		Order 1	No.		

	emben si de mer un voi de la derien su de la constitu		gan kanada k
Detroportion transformation to the accommission of the accommissio	anat communication and section 4: Confe to July 2014 (1994)	financio como de esteramente como circa con como de	от при

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Electronically Signed By: Diana Cannon

Title: Production Analyst

Date: 02/17/2004

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By: Ronald Eidson Date of Survey: 06/27/2002

Certificate Number: 3239



February 18, 2004

Oil Conservation Division 1301 W. Grand Ave. Artesia, NM 88210

Attention: Bryan Arrant

Re: Twix Fee Com #1

1980' FNL & 990' FEL Section 4, T-22S, R-27E Eddy County, New Mexico

Dear Bryan:

In reviewing the requirement of an H_2S contingency plan on the above referenced well we have determined the following: The H_2S concentration is 25 ppm in the Delaware, therefore no potentially hazardous volume exists. We do not believe that an H_2S contingency plan is necessary.

If you have questions or need further information, please call.

Sincerely,

Melanie J. Parker Land Department

/mp