

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
**Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.
NMNM98122

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

7. If Unit of CA/Agreement, Name and/or No.
NMNM071030A

2. Name of Operator
SANDRIDGE EXPL AND PROD. LLC

8. Well Name and No.
SKELLY UNIT #272

3a. Address
2130 W. BENDER
HOBBS, NM 88240

3b. Phone No. (include area code)
575-738-1739 EXT 117

9. API Well No.
30-015-29064

10. Field and Pool or Exploratory Area
GRAYBURG JACKSON; SR-Q-G-SA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

ULC SEC 28, T17S R31E 1213' FNL 1428' FWL



11. Country or Parish, State
EDDY

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☒ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Add Perfs
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	Seven Rivers
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1. Pull production equipment
2. RIH to check for fill (PBTD is 3943' and btm per is @3852')
3. If necessary, clean out any scale and fill to at least 3900'.
4. Run in w/RBP and set @2500'
5. Perforate Seven Rivers Formation (multiple intervals 2130'-2289')
6. Run treating packer and set above top perforation
7. Acidize w/4000 gals 15% Anti-Sludge HydroChloric Acid
8. Swab back load
9. Retrieve RBP - place on production in the Seven Rivers and GBSA (Grayburg-Jackson Pool [Seven Rivers-Queen-Grayburg-San Andres])



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Colleen Robinson

Title Regulatory Analyst

Signature

Date 11/08/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.