Subtitit 3 Copies To Appropriate District	State of New Me	•	Form C-103		
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		May 27, 2004 WELL API NO.		
District 11			30-015-26624		
1301 W. Grand Ave., Artesia, NM 88210 District III			5. Indicate Type of Lease STATE FEE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-255		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			GJ West Coop Unit		
PROPOSALS.)	ROPOSALS.) . Type of Well: Oil Well Gas Well Other			8. Well Number 92	
2. Name of Operator	Gas wen Guid		9. OGRID Number		
COG Operating LLC			229137		
3. Address of Operator 550 W Texas, Suite 1300, Midland, TX 79701			I 0. Pool name or Wildcat Grayburg Jackson, 7RVS-QN-G-SA - 1E50		
4. Well Location	d, 17 /9/01		Grayoting Jackson, 7R	V5-QN-G-5A 7/890	
Unit LetterJ	1650feet from theSout	h line and	2110 feet from	the East line	
Section28	Township 17S Ra	ange29E	NMPM	County Eddy	
	I 1. Elevation (Show whether DR, 3560.	RKB, RT, GR, etc.,			
Pit or Below-grade Tank Application) UK			
	vaterDistance from nearest fresh w	vater well Dis	stance from nearest surfac	e water	
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bb1s; Co	nstruction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON		COMMENCE DR	=	PAND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN			
OTHER:		OTHER: Amend		<u>\</u>	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
2-20-91 Perf 2741-4496. Acidized perfs 4145-4550 w/ 2000 gals 15% NE acid. Swab well					
2-21-91 Acidized perfs 2741-3456 w/ 4000 gals 10% NE acid. 2-22-91 Set CIBP @ 4103					
2-23-91 Set CIBF (# 4103) 2-23-91 Frac perfs 2741-3456 w/ 200,000 gals 40# gelled wtr, 500 sx 20/20, 1000 sx 8/16 sand Hinter ded Hinter ded					
3-04-91 RIH w/ tbg & rods. Set tbg @ 3500' and turned to produciton					
	:				
			•		
			•		
			-		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-					
	r closed according to NMOCD guidelines [
SIGNATURE		oduction Analyst		DATE 10/24/06	
Type or print name Diane Kuyken	dal l / E-mail addr	ess: dkuykendall@cor	nchoresources.com Tel	ephone No. (432) 683-7443	
For State Use Only)ada	Dust H.	5 100 120	2/4//	
APPROVED BY: Conditions of Approval (if any):	TITLE_	<u>Usi and</u>	Sperison	DATE 01/24/2011	