and the second s	and a second control of the second control of the second control of the second control of the second control of	AVOLEMENT TO THE SECOND	- 1.1.1.3.1.3.1.3.3.3.3.3.3.3.3.3.3.3.3.3
Number Office		, consideration of the second control of the second control of the second control of the second control of the	
OFFICE ON SEASONSERV POSSERV POSSERV POSSERVED SECTIONS OF SEASONSERVED SECTIONS OF SECTIO	RVATION DIVISION O, Box 2088	WELL API NO. 30-035-20026	
(min = 2 = 2 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1	w Mexico 87504-2088	5. Indicate Type of Leave STATE FEE	<u>X</u>)
NSTRICT III- OLO RE BRITO Rd., ADSOM NATIO 13 (III) 9 52	APR 3 0 1991	6. State Oil & Gás Léase No.	
SUNDRY NOTICES AND REPORT	IS ON WELLS O. C. D.		
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF DIFFERENT RESERVOIR. USE APPLICAT (FORM C-101) FOR SUCH PROP	TON FOR PERMIT	7. Lease Name or Unit Agreement Name	27
Type of Well: OL OAS WELL WELL X OTH	ER /	Virden Com #1 345	00-
Name of Operator	1464	& Well No.	
Cibola Energy Corporation \ Address of Operator	7 910	9. Pool name or Wildcat	
P.O. BOX 1668 Albuquerque	e. NM 87103	Wildcar	
Well Location			
Unit Letter _D : 100 Feet From The _No	OFFE Line and 95	Hed from the West	Line
Section 20 Township 14		NMPM Otero Coun	.y
10. Elevation	(Show whether DF, RKB, RT, GR, etc.)		
Check Appropriate Box to	o Indicate Nature of Notice, R	Report or Other Data	222
NOTICE OF INTENTION TO:		SEQUENT REPORT OF:	
	DON REMEDIAL WORK	ALTERING CASING	П
RFORM REMEDIAL WORK PLUG AND ABAN			_ [
JPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMEN	Ŧ 📋
LL OR ALTER CASING	CASING TEST AND C	EMENT JOB [X]	
HER:	OTHER:		. LJ
Concrete Proposed of Completed Operations (Clearly state all periods) SEE RULE 1103. WELL DRILLED TO 4,991 FT. A TO APPROXIMATELY 2460 AND WITH MUD BECAUSE ENCOUNTERED WAT RAN 4,986 FT. 5 1/2" CASING TO SCAVENGE HOLE. INTENT WITHAN 2,000 FT. OF SURFACE.	AND LOGGED. 7 7/8" WITH MUD FROM THERE TER AT 2460). G. CEMENTED CASING JAS THAT COMPETENT O	HOLE. (AIR DRILLED TO TD. SWITCHED TO WITH POZ MIX AHEAD DEMENT COME NO LESS	
MIXED TOO THICKLY AND CAUSE	ED CESSATION OF CEME DP OF CEMENT IN CASI REFORE, APPROXIMATEL ING. TOP OF CEMENT	ENT JOB WHEN TOP PLUG ING BELOW APPROXIMATELY LY 4,000 FT. OF CEMENT OUTSIDE PIPE UNKNOWN	lin din tentaja
SHUT IN PENDING NEGOTIATION		DRILLING OUT CEMENT.	the state of the s
needry certify that the information above is true and complete to the best of m		0.7 100 103	
ONATURE	PRODUCTION	CLERK 04/28/91	-
TE ORIPRINT NAME ANTHONY URQUIDEZ		тецелноме ма. 1-62	<u>5-0</u> 342
hu speed (in State Use)			204
mil blother	SUPERVISOR, I	DISTRICT II MAY 7 1) 4)