

CCW - Artesia

dhf

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
 J. Cleo Thompson

3a. Address
 P.O. Box 237 Loco Hills, 88255

3b. Phone No. (include area code)
 (505)677-2396

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
 T 17S R 30E Sec 4

5. Lease Serial No.
 LC 060325

6. If Indian, Allottee or Tribe Name
 N/A

7. If Unit or CA/Agreement, Name and/or No.
 West Square Lake Unit

8. Well Name and No.
 Tract 9 Well 13

9. API Well No.
 30-015-04081

10. Field and Pool, or Exploratory Area
 Grayburg-San Andreas

11. County or Parish, State
 Eddy, NM

1980' FSL + FEL

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-5 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

We propose to T.A. this well until our water flood is put in operation. We will properly T.A. as follows:

- 7" Csg set @ 2750'.
- Well has a water flow.
- Will pull pipe and pkr out of hole.
- Will go back in hole w/C.I.B.P. and set @ 2750' w/30' cmt on top.
- Will repair any Csg leaks.
- Test Csg to 500# as per BLM requirements.

RECEIVED
OCD ARTESIA

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed) Amador Pardo Jr. Title Production Foreman

Signature [Signature] Date 7-15-2000

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (OCD) JOE G. LARA Title Production Foreman Date 8/21/2000

Office CFO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.