

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

1. LEASE DESIGNATION AND SERIAL NO.

LC-028784-93-B

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

3. OPERATOR NAME

4. NAME OF LEASE NAME

Burch "BB" Federal

5. WELL NO.

25

6. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

7. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec. 18, 17-S, 30-E

8. COUNTY OR PARISH

Eddy

9. STATE

NM

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Phillips Petroleum Company

3. ADDRESS OF OPERATOR
4001 Penbrook Street, Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

Unit C, 660' FNL, 1893' FWL

14. PERMIT NO.
API No. 30-015-20562

15. ELEVATIONS (Show whether SW, SE, NE, etc.)
3658' RKB - 3648' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PLUG OR ALTER CASING
MULTIPLE COMPLETS
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) Set CIBP & TA wellbore

REPAIRING WELL
ALLOGGING CASING
ABANDONMENT*

X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

3-30-92: GIH with 3-7/8 bit and scraper on 2-3/8 workstring. Ran scraper to 2600'. COOH and run in with CIBP. Set plug at 2468'. Come up 5 ft. and circulate wellbore w/37 bbl KW132 mix with fresh water. Install recorder in system, press up casing to 500# for 15 min. Held OK. COOH w/workstring. Don Early w/BPM witness test. Well temp drop from report. Request permit to TA well for one year.

APPROVED FOR 12 MONTH PERIOD

ENDING 3/29/93

This Approval of Temporary Abandonment Expires

4/01/97 NMOC

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]
M. Sanders

TITLE Supv., Reg/Proration

DATE

04-01-92

(This space for Federal or State office use)

APPROVED BY

PETROLEUM ENGINEER

(915) 368-1488

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

4/8/92

*See Instructions on Reverse Side