

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**00-784**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sunray Oil Company</b>	8. Farm or Lease Name <b>State #0</b>
3. Address of Operator <b>P. O. Box 1116, Roswell, New Mexico</b>	9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM <b>West</b> LINE, SECTION <b>13</b> TOWNSHIP <b>19S</b> RANGE <b>28E</b> NMPM.	10. Field and Pool, or Wildcat <b>E. Millam-Queen Grayburg</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3376</b>	12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	OTHER <b>Perforate Additional Section</b> <input checked="" type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
	PLUG AND ABANDONMENT <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull tbg, pump and rods.
2. Perforate one (1) hole at each of the following depths: 2091', 2102', 2113', 2131', 2140' and 2150'
3. Acidize w/1000 gals BDA and frac w/20,000 gals of refined oil and 30,000# sand.
4. Ran tbg, rods and pump.
5. Put well on production.

**RECEIVED**  
**JUL 9 1965**  
**D. C. C.**  
**ARTESIA, OFFICE**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.J. Brawley **B.J. Brawley** TITLE District Engineer DATE June 30, 1965

APPROVED BY M.L. Armstrong TITLE OIL AND GAS INSPECTOR DATE JUL 9 1965

CONDITIONS OF APPROVAL, IF ANY: