

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P. O. BOX 12088  
SANTA FE, NEW MEXICO 87501  
FEB 21 1985  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
B-11339-10

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Bass Enterprises Production Co. ✓ 3. Address of Operator P. O. Box 2760, Midland, Tx 79702-2760 4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM East 1 LINE, SECTION 1 TOWNSHIP 19S RANGE 28E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3385.2' GL 3403.7' KB 12. County EDDY	7. Unit Agreement Name ----- 8. Farm or Lease Name Palmillo State Com 9. Well No. 1 10. Field and Pool, or Wildcat North Turkey Track Morrow (Gas)
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER Perforate & Acidize Morrow <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU Swab unit.
- Perforate intervals 10,997'-11,002' (20 Holes)' 11,006'-11,011' (20 Holes) 11,051'-11,054' (12 Holes).
- Acidize new perfs. w/3,000 Gals. 7½% Hcl acid.
- Flow or swab to clean up.
- Rig down swab unit.

Proposed starting date: upon Approval of Form - C-103.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.C. Davis TITLE Sr. Production Clerk DATE 2-18-85

Original Signed By  
Leslie A. Clements  
Supervisor District II

PROVED BY

DATE

FEB 25 1985

EDITIONS OF APPROVAL, IF ANY: