Submit 3 Copies to Appropriate District Office

Energy

State of New Mexico ierals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.		
30-015-2682	25	
S. Indicate Type of Lease		

DICTRICT II	Comto Co Mani Marian	275ハル_つハジ♀		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	awer DD, Artesia, NM 88210 CT III		5. Indicate Type of Lease STATE FEE XX 6. State Oil & Gas Lease No.	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name		
1. Type of Well:		./	, m	
MEIT X MEIT	OTHER		Thomas AJJ Com	
2. Name of Operator YATES PETROLEUM CORPORAT	'ION		8. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
105 South 4th St., Artes	ia, NM 88210	·	Dagger Draw Upper Penn, North	
4. Well Location Unit Letter : 1780	_ Feet From The North	Line and660	Feet From The <u>East</u> Line	
Section 8	Township 19S Ran	ge 25E	NMPM Eddy County	
	10. Elevation (Show whether L	OF, RKB, RT, GR, etc.)		
	3545' GR		<u> </u>	
	propriate Box to Indicate N			
NOTICE OF INTE	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER:		OTHER: Production casing & cement X		
12. Describe Proposed or Completed Operation work) SEE RULE 1103.	18 (Clearly state all pertinent details, and	d give pertinent dates, inclu	ding estimated date of starting any proposed	
TD 8250'. Reached TD a	t 12:45 AM 8-18-95.	Ran 201 joints	of 7" 26# & 23# casing as follow	
15 joints of 7" 26# N-8	0 LT&C (596.63'); 65	joints of 7" 2	6# J-55 LT&C (2684.19'); 92	
ioints of 7" 23# J-55 L	T&C (3786.30'); 26 jc	ints of 7" 26#	J-55 LT&C (1067.63') and 3	
joints of 7" 26# N-80 L	T&C (126.30') (Total	8261.05') of c	asing set at 8250'. Float	
shoe set at 8250'. Flo	at collar set at 8208	B'. DV tool se	t at 6902 Havker Joint set	
from 7732-7753'. Pump	out sub set at 8166'.	Cemented in	two stages as follows: Stage 5 sacks Super C4% CF-24%	
1: Fulliped 20 DDIS mud	TIUDII AND TO DOTO WITH	i i ancad or 45	5 Backs Baper o, 170 or 1, 170	
UF-14A, 3.42#/sack salt	for 20 minutes City	coulated 157 ca	13.0). , PD 323019958-19-95. cks. Circulated through DV tool	
for 2 hours Stage 2:	100 sacks "H" 127 t	hixad. 1/4#/sa	ck celloseal, 10#/pack/gilson-	
ite and 19 CaCl2 (vield	1.54. weight 14.6) a	and 755 sacks P	ace ter Lite C, 5#/sack gil-	
sonite. 1/4#/sack cello	seal and 5# salt (vie	1d 2.01, weigh	t 12.5). Tailed in with 100	
sacks "H" (vield 1.18.	weight 15.6). PD 7:0)9 PM 8-19-95.	Bumped plag to 3200 psi for	
2 minutes. Circulated	53 sacks. Released 1	ig at 12:00 AM	8-20-95. Waiting on completion	
I Harby certify that the information above is true as	ad complete to the best of my knowledge and l	belief.		
SIGNATURE Justin	fur m	Production (Clerk Aug. 21, 1995	
TYPEOR PRINT NAME Rusty Klein			<u>тецерноме но. 505/748-1</u> 4	
(This space for State Use)	NED BY TIM W. GUM			
ORIGINAL SIG	IPERVISOR		AUG 2 9 1995	
APPROVED BY	m	P	DATE	