

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+gsp
up

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-27040
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-2781

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name State CO Com
2. Name of Operator YATES PETROLEUM CORPORATION ✓	8. Well No. 8
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat North Dagger Draw U/Penn
4. Well Location Unit Letter C : 916 Feet From The North Line and 1980 Feet From The West Line Section 36 Township 19S Range 24E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3606' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Treat openhole perfs & add perfs <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to treat openhole and add perforations in Canyon Dolomite as follows:

1. TOOH w/tubing & pump. TIH w/tubing and packer. Set packer at 7740'.
2. Treat openhole section 7764-7864' w/3000 gallons 20% HCL with scale & paraffin inhibitor.
3. TOOH w/tubing & packer.
4. Perforate 7724-7693' w/36 holes as follows: 7724, 26, 28, 29, 32, 34, 36, 38, 40, 7674, 75, 78, 80, 82, 84, 87, 91 & 7693' (2 SPF) (Canyon Dolomite).
5. TIH w/tubing, packer & RBP.
6. Straddle perforations 7724-40' and acidize with 600 gallons 20% HCL and ball sealers.
7. Straddle perforations 7674-93' and acidize with 600 gallons 20% HCL and ball sealers.
8. Set RBP at 7750' and packer at 7650'.
9. Treat perforations 7674-7740' w/20000 gallons 20% HCL with scale & paraffin inhibitor.
10. TOOH w/RBP & TIH w/tubing & packer. Swab and evaluate.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE June 28, 1993

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY MIKE WILLIAMS DATE JUL 5 1993

APPROVED BY SUPERVISOR, DISTRICT II TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: