

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Encl Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-28370
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-10167
7. Lease Name or Unit Agreement Name Boyd X State
8. Well No. 6
9. Pool name or Wildcat Dagger Draw Upper Penn, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line Section 29 Township 19S Range 25E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3512' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Spud, resume drilling, surface casing and cement <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 26" hole with rat hole machine, at 11:30 AM 3-29-95. Cemented to surface. NOTE: Notified OCD - Artesia of spud. Resumed drilling a 14-3/4" hole with rotary tools at 1:15 AM 4-1-95. Reached TD of 14-3/4" hole at 9:45 AM 4-3-95. Ran 26 joints of 9-5/8" 36# 8rd J-55 ST&C (1168.42' on casing set at 1163'. 1-Texas Pattern notched guide shoe set at 1163'. Insert float set at 1119'. Cemented with 200 sacks "H", 12% thixad, 1/4#/sack celloseal, 10#/sack gilsonite and 2% CaCl2 (yield 1.56, weight 14.6) and 900 sacks Pacesetter Lite "C", 1/4#/sack celloseal, 10#/sack gilsonite (yield 1.84, weight 12.7). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 6:00 PM 4-3-95. Bumped plug to 1000 psi, OK. Circulated 130 sacks cement. WOC. Drilled out at 4:00 AM 4-5-95. WOC 34 hours. Nippled up and tested to 3000 psi for 15 minutes, OK. Reduced hole to 8-3/4". Resumed drilling. NOTE: Cement job witnessed by OCD - Artesia.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 4-12-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL FILED BY THE NM. OCD

APR 14 1995

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: