

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-28717
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. Property Code 7913
7. Lease Name or Unit Agreement Name State "B"
8. Well No. 3
9. Pool name or Wildcat Dagger Draw Upper Penn. North (15472)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Mewbourne Oil Company	
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>850</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>19S</u> Range <u>25E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3468' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/02/96 Drilled 8-3/4" production hole to a TD of 7,950'. Ran E-Logs and evaluated same. Decided to plug well. Set following cement plugs as Artesia NMOCD office instructed: 40 sks. @ TD of 7,950', 100' plug @ 6,283', 100' plug @ 5610', 100' plug @ 3,550', 100' plug @ 2,350', 100' plug @ 1241' (50' inside and outside of 9-5/8" csg.) WOC 4 hours on this plug and tagged top @ 1,090', 300' plug @ 750', 10 sk. plug @ surface. Cut off wellhead, installed dry hole marker. Rig released @ 6:00 a.m. 1/03/96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill Pierce TITLE Drilling Superintendent DATE 1/03/96
(505)
TELEPHONE NO. 393-5905

TYPE OR PRINT NAME Bill Pierce

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT H SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 8 1996

CONDITIONS OF APPROVAL IF ANY: