N.M. Oil C 3. Division

clsi

Form	3	160)-5
(June	1	99	0)

UNITED STATES 811 S. 1st Street
DEPARTMENT OF THE INTERIOR Artesia, NM 88210-2834
BUREAU OF LAND MANAGEMENTARTESIA, NM 88210-2834

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.				
LC 029387B				
6. If Indian, Allottee or Tribe Name				

SUNDRY	NOH	JES ANL	KEPOKI	S UN	WELL2	

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

]
1. Type of Well Oil Gas Well Well Other	*	8. Well Name and No.
2. Name of Operator ✓	The state of the s	West Shugart '30' Federal #1
CONCHO RESOURCES INC.	2000 3	9. API Well No.
3. Address and Telephone No.	7/FO. 3/	30015-29166
110 W LOUISIANA STE 410; MIDLAND TX 7970	11 3/4 <u>6</u> 5/	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Descript	tion)	Wildcat; Shugart SW Bone Spring
1980' FNL & 1980' FWL, Sec. 30, T-18S, R-31E		11. County or Parish, State
		Eddy, NM
12. CHECK APPROPRIATE BOX(s) TO	O INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	ON
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
L. I mai Abandominent Rouce		· ·
	Other	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)*

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO PLUG BACK THE WEST SHUGART '30' FEDERAL NO. 1 WELL ACCORDING TO THE FOLLOWING PROCEDURE:

1. MIRU. POOH w/ rods & pump.

- 2. RIH w/ CIBP & set @ 10,100'. Dump 35' sx cmt on top. (Abandoning Morrow pool).
- 3. RIH w/ 4" csg gun & perf Bone Spring w/ 2 SPF @ 8176-84', 8202-18' (50 shots).
- 4. Acidize zone w/ 2500 gals 15% NEFE.
- 5. RU swab and test zone.
- 6. Put well on pump.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.