Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

c	51	
	h .	
	y	
	٧′	

Form C-103 Revised 1-1-89

γ'
WELL API NO.
30-015-30434
5. Indicate Type of Lease
STATE K FEE
6. State Oil & Gas Lease No. VA - 1541
7. Lease Name or Unit Agreement Name
Little Box State
8. Well No.
3
9. Pool name or Wildcat
Little Box Canyon - Morrow
1090 For Francisco III - 1
1980 Feet From The West Line
NMPM Eddy County
Report, or Other Data
BSEQUENT REPORT OF:
ALTERING CASING
IG OPNS. U PLUG AND ABANDONMENT U
EMENT JOB
oletion
cluding estimated date of starting any proposed
oth of 8120' - circulate hole
en of offe effectate note
rate 4 spf from 7926' - 7950'
'2" HCL - fluid to surface in
with FTP = 1500 ps 5679
with FTP = 1500 335678970
/ N° //
ootential. // o 🔼
ootential.
octential. OCD - A RECE OCD - A

<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION 310 Old Santa Fe Trai		WELL API NO.
DISTRICT II	Santa Fe, New Mexi		30-015-30434
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X PEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE K FEE 6. State Oil & Gas Lease No.
1000 RU BILLOS RU., AZIO., NW. 67410			VA - 1541
SUNDRY NO	TICES AND REPORTS ON WEL	LS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BY DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
	ENVOIRE USE "APPLICATION FOR PEI C-101) FOR SUCH PROPOSALS.)	HIMI I	
1. Type of Well:			1
MET WET X	OTHER		Little Box State
2. Name of Operator			8. Well No.
Stevens & Tull,	Inc.		3
3. Address of Operator P. O. Boy 11005	Midland, TX 79702		9. Pool name or Wildcat
4. Well Location	Fidiald, IX 79702		Little Box Canyon - Morrow
Unit Letter F : 19	80 Feet From The North	Line and	1980 Feet From The West Line
			Zan
Section 36			NMPM Eddy County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	4408 GR	Varana aCNI adia a D	VIIIIIIIII
	Appropriate Box to Indicate 1		_
NOTICE OF IN	TENTION TO:	508	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS	CASING TEST AND CE	
PULL OR ALTER CASING OTHER:		CASING TEST AND CE	EMENTJOB Letion x
PULL OR ALTER CASING OTHER:		CASING TEST AND CE	MENTJOB .
OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103.	rations (Clearly state all pertinent details, o	CASING TEST AND CE OTHER: Compl and give pertinent dates, inc	etion x Letion x Luding estimated date of starting any proposed
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w	ith 252 joints 2 3/8" t	CASING TEST AND CE OTHER: Compl and give pertinent dates, inc	EMENTJOB Letion x
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w	rations (Clearly state all pertinent details, o	CASING TEST AND CE OTHER: Compl and give pertinent dates, inc	etion x Letion x Luding estimated date of starting any proposed
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean	ith 252 joints 2 3/8" twith 4% KCL.	CASING TEST AND CE OTHER: Compl and give pertinent dates, including to a dept	Letion x Inding estimated date of starting any proposed th of 8120' - circulate hole
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w	ith 252 joints 2 3/8" twith 4% KCL.	CASING TEST AND CE OTHER: Compl und give pertinent dates, including to a dept	EMENT JOB Letion Luding estimated date of starting any proposed The of 8120' - circulate hole Eate 4 spf from 7926' - 7950'
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated	CASING TEST AND CE OTHER: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2	Letion x Inding estimated date of starting any proposed th of 8120' - circulate hole
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operwork) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minut	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in	CASING TEST AND CE OTHER: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2 6 minutes.	Letion x Inding estimated date of starting any proposed The of 8120' - circulate hole That 4 spf from 7926' - 7950' 2" HCL - fluid to surface in
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operwork) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minut	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated	CASING TEST AND CE OTHER: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2 6 minutes.	Letion x Inding estimated date of starting any proposed The of 8120' - circulate hole That 4 spf from 7926' - 7950' 2" HCL - fluid to surface in
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minutes 11/18/98 - Estimates 11/18/9	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on	casing Test and ce other: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2 6 minutes.	Letion x Letion x Luding estimated date of starting any proposed The of 8120' - circulate hole The state 4 spf from 7926' - 7950' 2" HCL - fluid to surface in With FTP = 1500 ps 1678970
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minutes 11/18/98 - Estimates 11/18/9	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in	casing Test and ce other: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2 6 minutes.	Letion x Letion x Luding estimated date of starting any proposed The of 8120' - circulate hole The state 4 spf from 7926' - 7950' 2" HCL - fluid to surface in With FTP = 1500 ps 1678970
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minutes 11/18/98 - Estimates 11/18/9	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on	casing Test and ce other: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2 6 minutes.	Letion x Letion x Luding estimated date of starting any proposed The of 8120' - circulate hole The state 4 spf from 7926' - 7950' 2" HCL - fluid to surface in With FTP = 1500 ps 1678970
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minutes 11/18/98 - Estimates 11/18/9	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on	casing Test and ce other: Compl and give pertinent dates, including to a dept tim-gum, perfor in 2 bbls 7 1/2 6 minutes.	Letion Letion
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minuments of the second of th	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on	casing test and ce other: Completed	Letion x Letion x Luding estimated date of starting any proposed The of 8120' - circulate hole The state 4 spf from 7926' - 7950' 2" HCL - fluid to surface in With FTP = 1500 ps 1678970
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minuments of the second of th	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on o do 72 hour build-up to the best of my knowledge and be and complete to the best of my knowledge and be	CASING TEST AND CE OTHER: Compl and give pertinent dates, incomplete tim-gum, perform in 2 bbls 7 1/2 6 minutes. 30/64" choke we sest and 4 pt position.	Letion x Letion
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minuments of the second of th	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on o do 72 hour build-up t	CASING TEST AND CE OTHER: Compl and give pertinent dates, incomplete tim-gum, perform in 2 bbls 7 1/2 6 minutes. 30/64" choke we sest and 4 pt position.	Letion x Letion
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/16/98 - RIH w clean 11/17/98 - POH w Total 3 minutes and 11/18/98 - Estimates 11/19/98 - SWI t	ith 252 joints 2 3/8" twith 4% KCL. ith tubing - RIH with s 96 holes - perforated utes, gas to surface in ated flow at 5 mmcfd on o do 72 hour build-up to the best of my knowledge and be and complete to the best of my knowledge and be	CASING TEST AND CE OTHER: Compl and give pertinent dates, incomplete tim-gum, perform in 2 bbls 7 1/2 6 minutes. 30/64" choke we sest and 4 pt position.	Letion x Letion

APPROVED BY-

ORIGINAL SIGNED BY TIM W. GUI

1-20-99