

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE ORIGINAL COPY
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-070286

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
PENNZOIL COMPANY ✓

8. FARM OR LEASE NAME.

Hudson-Federal 33

3. ADDRESS OF OPERATOR
1007 Midland Savings Building, Midland, Texas 79701

9. WELL NO.

2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

Undesignated Penn.

1980' FSL, 1650' FWL, Sec. 33, T-20-S, R-30-E

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 33, T-20-S, R-30-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3381.4 GL

12. COUNTY OR PARISH
Eddy

13. STATE
N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
FULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/28/67 - Drilled 7-7/8" hole to 11,632'. No commercial production found. Plugged and abandoned as follows:

- Plug #1 - 32 sacks 11,290 - 11,140'
 - Plug #2 - 23 sacks 10,035 - 9,935'
 - Plug #3 - 23 sacks 7,803' - 7,703'
 - Plug #4 - 23 sacks 5,510 - 5,410'
 - Plug #5 - 23 sacks 4,071 - 3,971'
 - Plug #6 - 23 sacks 1,965 - 1,865'
 - Plug #7 - 225 sacks 1,365 - 450'
 - Plug #8 - 10 sacks top of surface
- Cut off casing and set dry hole marker.
Job complete at 12:00 noon 5/29/67.

RECEIVED
JUN 19 1967
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Drilling Superintendent DATE 6/2/67

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL IF ANY:

APPROVED

[Signature]
R. L. L. AN

*See Instructions on Reverse Side

RECEIVED
JUN 16 1967

U. S. GEOLOGICAL SURVEY
WELL, NEW MEXICO