

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OPERATOR'S COPY

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well  
Oil Gas  
 Well  Well  Other

2. Name of Operator  
**STRATA PRODUCTION COMPANY**

3. Address and Telephone No. **P. O. Box 1030  
Roswell, New Mexico 88202-1030 505-622-1127**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
**1875' FSL & 1765' FWL  
Section 25-20S-28E**

5. Lease Designation and Serial No.  
**NM-17103**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.  
**Lee Federal #6**

9. API Well No.  
**30-015-24891**

10. Field and Pool, or Exploratory Area  
**Scanlon Delaware**

11. County or Parish, State  
**Eddy County, New Mexico**

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	OTHER _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

04/11/00: TOH with rods, pump and tubing.

04/13/00: Set CIBP at 5400' and cap with 25' cement. Set CIBP at 2565' and cap with 25' cement. Set CIBP at 410' and cap with 25' cement.

04/15/00: Set 60' Class "C" Neat cement plug at surface. Prep to set Dry Hole Marker and finalize. Well is Plugged and Abandoned.

Witnessed and approved by Jim Amos with the Carlsbad BLM.

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

pd A  
2-19-01

14. I hereby certify that the foregoing is true and correct

Signed Carol G. Garcia Title Production Records Manager Date 05/17/2000

(This space for Federal or State office use)

Approved by Alexis C. Swoboda Title PETROLEUM ENGINEER Date MAY 22 2000

Conditions of approval, if any:

