



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Artesia

Lease No. LC-071066

Unit M

RECEIVED  
30-815-03728  
APR 6 1960

SUNDRY NOTICES AND REPORTS ON WELLS  
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 1, 1960

Hanson-Federal Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 12

SW/4 of SW/4 (1/4 Sec. and Sec. No.) T-26-S (Twp.) R-29-E (Range) 10PM (Meridian)

(Brushy Draw (Field) Eddy County (County or Subdivision) New Mexico (State or Territory))

The elevation of the derrick floor above sea level is 3,005 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Propose to drill a Delaware Sand test. Set a minimum of 250' of 10 3/4" casing and cement with sufficient quantity to get returns on the surface. Drill to approx. 3300' to test the Delaware Sand. Run 2 1/2" casing and cement with sufficient volume to fillup in excess of 500' of annular volume. Perforate the oil zone in the Delaware Sand and acidize and sand-frac w/ 1000 gals of refined oil and 1000# of sand. Swab or flow well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Curtis Hankamer

Address 1422 Bank of the Southwest

Houston 2, Texas

By Curtis Hankamer  
Curtis Hankamer  
Title Operator

