Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103	
Office District I	Energy, Minerals and Natural Resources			Revised May 08, 2003	
1625 N. French Dr., Hobbs, NM 88240	-			WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	rand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-015-23942 5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.			STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505 DHC-3042			LG-16	37	
SUNDRY NOTICES AND REPORTS ON WELLS					or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				NEW MEXICO DC STATE	
1. Type of Well:			8. Well Number		
Oil Well X Gas Well	Other	R	ECEIVED		1
2. Name of Operator			IAR 1 0 2004	9. OGRID Numb	per
MARBOB ENERGY CORPORA	TION				14049
3. Address of Operator	ND/ 00011 0007	OC	D-ARTESIA	10. Pool name or	l l
PO BOX 227, ARTESIA, NM 88211-0227 4. Well Location					UPPER PENN &
4. Well Location PALMILLO; WOLFCAMP, WEST					
Unit Letter H :	1980 feet from the	NORT	H line and	660 feet fro	om the <u>EAST</u> line
Section 18 Township 19S Range 29E NMPM County EDDY					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3379' KB  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO:    SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	П	REMEDIAL WOR		ALTERING CASING
TEN ON THE WEDIAL WORK	1 LOG / IND / ID/ INDON	u			ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN	ND 🗆	ABANDONMENT
FULL ON ALTER CASING	COMPLETION	Ш	CEMENT JOB	<b>1</b> 0	
07115		_	071150	DHC-3042	
OTHER:		<u> </u>	1	HOLE COMMING	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
01 100011p1011011					e e
DOWNHOLE COMMI	NGLE AS FOLLOWS:				
2/18/04 - RETRIEVE RBP.					
2/20/04 - ACIDIZE PERFS @ 9558' - 9962' WITH 3000 GAL 15% NEFE ACID					
WITH 1000 GAL XYLENE MIXED WITH IT. ACIDIZE PERFS @					
9178' - 9291' WITH 1500 GAL 15% NEFE ACID WITH 500 GAL					
XYLENE MIXED WITH IT.					
2/24/04 - LEFT WELL PUMPING TO BATTERY.					
DOWNHOLE COMMINGLING @ 8941' - 9962'.					
SEE ADMINISTRATIVE ORDER DHC-3042.					
SEE ADMINISTRATIVE UNDER DRG-3042.					
I hereby certify that the information of	nove is true and complete	to the he	et of my knowledge	and belief	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE MANAGEMENT	Mun 1	TTLE	PRODUCTION AN	NALYST	_DATE3/9/04
Tomo and since the same of the	T CANNON			<b>-</b> .	(FOF) =10 000
<del></del>	J. CANNON			Teleph	none No. (505) 748-3303
(This space for State use)	TAN BELE-				MAD # 0 000
APPPROVED BY	FOR RECOR	as <sub>e</sub> on	LY		DATE 1 6 2004
Conditions of approval, if any:					