

rm 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Cons.  
N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use 'APPLICATION FOR PERMIT' for such proposals

5. Lease Designation and Serial No.

NM 0199070A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

14-08-0001-16056

8. Well Name and No.

Double L Queen Unit #02 I

9. API Well No.

30-005-20348

10. Field and Pool, or Exploratory Area  
Double L; Queen (Assoc)

11. County or Parish, State

Chaves, NM

SUBMIT IN TRIPLICATE

RECEIVED

MAR 28 2004

OGD-ARTESIA

1. Type of Well  
Oil Gas  
Well Well Other INJECTION

2. Name of Operator  
TIPTON OIL & GAS ACQUISITIONS

2. Address  
P.O. BOX 1234, LOVINGTON, NM 88260

Telephone No.  
505-631-4121

3. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter J  
Sec. 31, T14S, R30E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other CONVERT INJECTOR TO PRODUCER

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Release tbg. from permanent packer. POOH with tbg. GIH with work string and bailer. Knock packer to bottom of hole. POOH with work string and bailer. Run new rods, pump, and tbg. Set pumping unit and commence production.

14. I hereby certify that the foregoing is true and correct

Signed

*Dubiri McKelvey*

Title

SECRETARY TREASURER

Date 2/26/04

(This space for Federal or State office use)

Approved by

*CE*

Title

PIE

Date

3/18/04

Conditions of approval, if any: