

RECEIVED

MAY 03 2004

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OCD-ARTESIA

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 38-015-26350

5. Indicate Type of Lease
 STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
CARRASCO #14

8. Well No. 3

9. Pool name or Wildcat
E. LOVING (BRUSHY CANYON)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well ☒ Gas Well ☐ Other

2. Name of Operator PAU ENERGY, INC.

3. Address of Operator 5100 E. SKELLY DR. STE. 600
 TULSA, OK 74136

4. Well Location
 Unit Letter H 1980 feet from the NORTH line and 560 feet from the EAST line
 Section 14 Township 23S Range 28E NMPM County EDDY

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
2964' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	OTHER: <u>PLUG BACK & RECOMPILE</u>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 05/06/03 WITH USH. UNSEAT PUMP - PCH LD RODS & PUMP. NO WH & NH BOPE 05/08/03 TOH W/TBG. LD 46 JTS. 05/09/03 PU EVL - RAN GRAB TO 6100' - RAN & SET CTRP AT 6085'. LOAD & TEST CSG TO 1000# OK. PERF BRUSHY CANYON 4747-53', 4763-82', 4787-90' (60 HOLES). TEST TBG IN HOLE W/TKR TO 7000#. SET PRR @ 4664'. SWAB TBG DEY. 05/12/03 SITP 350# BLEED OFF. SWAB - IFL 2300' - SWAB DEY - GOOD OIL CUT. ACIDIZE PERFS W/2000 GAL 12 1/2 % HCL & 9 1/2 % BS - 8' BLWTR - FLOW BACK 33 BF & SWAB 28 BF - LACK 20 BF. 05/13/03 SWAB DEY 14 BF - LACK 6 BF. 05/14/03 SWAB DEY 10 BF. 05/15/03 - PU TREATERS - FRAC PERFS W/30,000 GAL XL GEL, 58760# 16/30 PR SD & 21,000# 16/30 PR SD - TAGGED W/RA MAT'L - 723 BFTR. 05/16/03 RAN TA LOG TO CHECK FRAC - FLOWED WELL - DEY 78 BF. 05/17/03 REL PRR & TOH.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nike Kaiser TITLE OP ENGR DATE 04/27/04
 Type or print name NIKE KAISER Telephone No. (918) 663-2800
 (This space for State use)

APPROVED BY FOR RECORDS ONLY DATE MAY 04 2004
 Conditions of approval, if any:

RUN PROD BHA BACK - TAC @ 4570' & SN @ 4725' - RAN RODS & PUMP - PER. 06/01/03 24 HR. TEST - 84 BO, 63 BW & 40 MCF GAS.