

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

RECEIVED

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

JUN 07 2004

2. Name of Operator

BP America Production Company

3a. Address

P.O. Box 1089 Emice NM 88231

3b. Phone No. (include area code)

505.394.1600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL C, 990' FNL & 2310' FWL
Section 9, T18S, R27E

5. Lease Serial No.

NM031186

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Empire Abo Unit 6

9. API Well No.

30.015.00838

10. Field and Pool, or Exploratory Area

Empire Abo

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☒ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other MIT

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD: 5670' PED: 5641' CIBP: 5273' PERFS: 5330-5584'

05.24.04: MIRUPU. NOWH. THREADS BAD. SD WAITING ON SPEAR.

05.25.04: SPEAR WH. NUBOP. TALLY TBG OUT OF HOLE. RUWL. SET CIBP @ 5273'.
DUMP 35' CMT ON TOP OF CIBP. SDON.

05.26.04: RIH & CIRC PKR FLUID. TESTED CSG TO 500#. HELD OK. DID NOT CUT CHART.
LD TBG. NDBOP. NOWH. JOB COMPLETE.

06.02.04: LOAD & TEST CSG TO 590#. HELD 30 MINS. HELD OK. XC OF CHART ATTACHED.
MIT WITNESSED BY BLM REPRESENTATIVE.

BP AMERICA PRODUCTION COMPANY REQUESTS PERMISSION TO MAINTAIN TA STATUS.
ALL WELLS IN THE EMPIRE ABO UNIT ARE CURRENTLY BEING EVALUATED AND INTEREST
OWNER APPROVAL IS BEING OBTAINED TO PROVIDE FUNDING TO EXPLORE FUTURE WORKOVER
POTENTIAL OR ABANDONMENT PACKAGES.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Kellie D. Murrish

Title

Staff Support

Date

06.04.04

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

