Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office March 4, 2004 Energy, Minerals and Natural Resources District 1 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-015-00258 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Nix Curtis JF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: RECEIVED Oil Well X Gas Well Other JUN 2 1 2004 2. Name of Operator 9. OGRID Number 025575 Yates Petroleum Corporation OCD ARTESIA 10. Pool name or Wildcat 3. Address of Operator 105 South Fourth Street, Artesia, NM 88210 Penasco Draw San Andres Yeso 4. Well Location Unit Letter D 990 feet from the West line feet from the North line and **Township** 18S Range **NMPM** Eddy County Section 32 26E 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3413'GR Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well_ Distance from nearest surface water Below-grade Tank Location UL_ Sect Two feet from the feet from the line and 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. **PLUG AND TEMPORARILY ABANDON** CHANGE PLANS **ABANDONMENT** MULTIPLE CASING TEST AND PULL OR ALTER CASING COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Yates Petroleum Corporation plans to plug and abandon this well as follows: Call OCD in Artesia with a 24 hr notice before commencing operations 1. Rig up all H2S safety equipment. No casing recovery will be attempted. Set 5-1/2" CIBP at 2635' with 35' Class "C" cement on top. Tag plug, load hole with plugging mud. Keep wellbore loaded with mud.
Spot 40 sx Class "C" plug from 1925'-2292'. WOC 2.5 hrs and tag plug. Reset if necessary. This will set a plug across the surface casing shoe and across the Glorieta top.
TIH to 140' and spot 15 sx Class "C" plug from 140' to surface. WOC 24 hrs and tag plug. 5. Remove all surface equipment and weld dry hole marker per regulations. NOTE: Yates Petroleum Corporation will use steel pits and no earth pits I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines ___, a general permit ___ or an (attached) alternative OCD-approved plan ____. TITLE: Regulatory Compliance Supervisor DATE: June 17, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471_ (This space for State use) TITLE Field Suspention APPPROVED BY Conditions of approval, if any:



