Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office	Energy, Minerals and Natural Re	sources	March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II	OIL CONSERVATION DIV	ISION 30-015-33258	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis I	5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410		SIAIL [FEE 🛛
District IV	Santa Fe, NM 87505	6. State Oil & Ga	s Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	CES AND REPORTS ON WELLS		Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUG BAC	CK TO A WC "3"	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FOR STIC	31476	
1. Type of Well:	29 ¹⁰ .	8. Well Number	
Oil Well Gas Well	Other	#3	1
2. Name of Operator	/49	2004 9. OGRID Numb	er
CHI OPERATING, INC	m RECE	N)	
3. Address of Operator	0702 OCD - A	V	Wildcat
P.O. BOX 1799 MIDLAND, TX, 79	9702	\\\\\	
4. Well Location	16.	10	
	OE 6>0-	797	
Unit Letter P: 660	feet from the SOUTH line	660' feet from the	EAST_line
Section 3		NMPM County	EDDY
	11. Elevation (Show whether DR, RKB)	RT, GR, etc.)	
Pit or Below grade Tonk Application (For	3165'- GR pit or below-grade tank closures, a form C-144	must be attached)	
			, , , ,
	RngPit typeDepth to		arest fresh water well
	Below-grade Tank Location ULS	ectTwpRng;	
1	Cont Commande No.		i i
feet from theline and	ieet from theime		
feet from theline and	teet from theine		
		of Notice Papert or Other I	Poto
12. Check	Appropriate Box to Indicate Nature	•	
12. Check A	Appropriate Box to Indicate Nature TENTION TO:	SUBSEQUENT REI	PORT OF:
12. Check	Appropriate Box to Indicate Nature TENTION TO:	SUBSEQUENT REI	
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM	SUBSEQUENT REI	PORT OF:
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REN CHANGE PLANS COI	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS MORE TO THE SUBSECTION OF THE SU	PORT OF: ALTERING CASING []
12. Check ANOTICE OF IN	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REN CHANGE PLANS COI MULTIPLE CAS	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND	PORT OF: ALTERING CASING PLUG AND
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REN CHANGE PLANS COI MULTIPLE CAS	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS MORE TO THE SUBSECTION OF THE SU	PORT OF: ALTERING CASING PLUG AND
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CAS COMPLETION CEN	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB	PORT OF: ALTERING CASING PLUG AND
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CAS COMPLETION OTH	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER:	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CASC COMPLETION OTHered operations. (Clearly state all pertine)	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: ent details, and give pertinent date	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CAS COMPLETION OTH	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: ent details, and give pertinent date	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CEM OTHER eted operations. (Clearly state all pertiners). SEE RULE 1103. For Multiple Completed operations.	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: ent details, and give pertinent date inpletions: Attach wellbore diagra	PORT OF: ALTERING CASING PLUG AND ABANDONMENT s, including estimated date am of proposed completion
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THER: 13. Describe proposed or completion of starting any proposed work or recompletion. Notified OCD of intent to spud @ 14	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CHANGE PLANS COMPLETION CHANGE PLANS CEM COMPLETION CEM CHANGE PLANS CEM COMPLETION CEM CHANGE PLANS CEM COMPLETION CEM COMP	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MERE: Cont details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion ole to 496'. Set 13 3/8"-
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION CEM OTHER eted operations. (Clearly state all pertiners). SEE RULE 1103. For Multiple Completed operations.	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: Sent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h pps CF. Tail: 150 sks ""C"+2% (PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: Ent details, and give pertinent date inpletions: Attach wellbore diagra is CDT on 7/03/04. Drill 17 ½" h pps CF. Tail: 150 sks ""C"+2% C on 7/04/04 @ 21:30 hrs CDT, diagra	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5
12. Check ANOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COM MULTIPLE CAS CEM COMPLETION CTM eted operations. (Clearly state all pertine of the complete of the compl	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: Ent details, and give pertinent date inpletions: Attach wellbore diagra is CDT on 7/03/04. Drill 17 ½" h pps CF. Tail: 150 sks ""C"+2% C on 7/04/04 @ 21:30 hrs CDT, diagra	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB MER: ent details, and give pertinent date inpletions: Attach wellbore diagra is CDT on 7/03/04. Drill 17 ½" h inpos CF. Tail: 150 sks ""C"+2% (inpletions) on 7/04/04 @ 21:30 hrs CDT, dia id.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Des, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION MULTIPLE CASCEM COMPLETION CHANGE PLANS CEM OTHER CHANGE PLANS CEM COMPLETION CHANGE PLANS C	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature of TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COMPLETION MULTIPLE CASCEM COMPLETION CHANGE PLANS CEM OTHER CHANGE PLANS CEM COMPLETION CHANGE PLANS C	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS. SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4. my knowledge and belief. I furthe neral permit or an (attached) alternal	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to ar certify that any pit or belowative OCD-approved plan
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COM MULTIPLE CAS COMPLETION CEM OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com :30 hrs CDT 7/3/04. Spud well 23:00 hrs: 350 sks "C"+4% Gel+2% CaCL2+.25; 0 hrs-7/05/04. Notified OCD of cmt job id drilling out cmt @ 05:00 hrs CDT 7/6/05 above is true and complete to the best of closed according to NMOCD guidelines , a ge	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Des, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to Description of the completion of the careful of
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COM MULTIPLE CAS COMPLETION CEM OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com :30 hrs CDT 7/3/04. Spud well 23:00 hrs: 350 sks "C"+4% Gel+2% CaCL2+.25; 0 hrs-7/05/04. Notified OCD of cmt job id drilling out cmt @ 05:00 hrs CDT 7/6/05 above is true and complete to the best of closed according to NMOCD guidelines , a ge	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS. SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4. my knowledge and belief. I furthe neral permit or an (attached) alternate DATE 7/6/04	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Des, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to Description of the completion of the careful of
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COM MULTIPLE CAS CEM COMPLETION CEM CHANGE PLANS CEM COMPLETION CEM COM	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS. SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4. my knowledge and belief. I furthe neral permit or an (attached) alternate DATE 7/6/04	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Des, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to Description of the completion of the careful of
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COM MULTIPLE CAS CEM COMPLETION CEM CHANGE PLANS CEM COMPLETION CEM COM	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS. SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4. my knowledge and belief. I furthe neral permit or an (attached) alternate DATE 7/6/04	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Des, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to Description of the completion of the careful of
12. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON T	Appropriate Box to Indicate Nature TENTION TO: PLUG AND ABANDON REM CHANGE PLANS COM MULTIPLE CAS COMPLETION CEM OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com :30 hrs CDT 7/3/04. Spud well 23:00 hrs: 350 sks "C"+4% Gel+2% CaCL2+.25; 0 hrs-7/05/04. Notified OCD of cmt job id drilling out cmt @ 05:00 hrs CDT 7/6/05 above is true and complete to the best of closed according to NMOCD guidelines , a ge	SUBSEQUENT REI MEDIAL WORK MMENCE DRILLING OPNS. SING TEST AND MENT JOB BER: ent details, and give pertinent date inpletions: Attach wellbore diagra s CDT on 7/03/04. Drill 17 ½" h ops CF. Tail: 150 sks ""C"+2% (on 7/04/04 @ 21:30 hrs CDT, dia 4. my knowledge and belief. I furthe neral permit or an (attached) alternate DATE 7/6/04	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Des, including estimated date am of proposed completion cole to 496'. Set 13 3/8"- CaC12+.25 pps CF. Circ 5 d not witness. Tst hd to Description of the completion of the careful of