

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

RECEIVED

MAY 17 2004

WELL API NO.
30-015-25654

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
LOWE STATE GAS COM

8. Well No.
2

9. Pool name or Wildcat
INDIAN BASIN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
KERR MCGEE OIL & GAS ONSHORE LLC

3. Address of Operator
16666 NORTHCHASE, HOUSTON, TEXAS 77060

4. Well Location
Unit Letter S : 330 Feet From The SOUTH Line and 330 Feet From The WEST Line

Section 36 Township 21S Range 23E NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
N / A

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-16-04
SET CIBP @ 8650 SPOT 20 SKS ON TOP
4-19-04
SPOT 35 SKS @ 7300 WOC & TAG @ 7080
SPOT 40 SKS 6500-6400
PULL 7" FROM 3498'
4-21-04
SPOT 75 SKS @ 3550 WOC & TAG @ 3380
SPOT 60 SKS 2050 WOC & TAG @ 1906
4-22-04
SPOT 60 SKS @ 375
SPOT 30 SKS 63-SURFACE INSTALL P&A MARKER CIRCULATE MUD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeff Kester TITLE CEMENTER / AGENT DATE 4-22-04

TYPE OR PRINT NAME JEFF KESTER / DAVID A. EYLER (432) 687-3033 TELEPHONE NO. 432-547-2926

(This space for State Use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE AUG 5 2004

CONDITIONS OF APPROVAL, IF ANY:



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor

8-2-04
OK to release
/s/

RECEIVED

JUL 1 5 2004

Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

19 May 2004

**OIL CONSERVATION
DIVISION**

RECEIVED

JUL 28 2004

OCD-ARTESIA

KERR MCGEE OIL & GAS ONSHORE LLC
16666 NORTH CHASE,
HOUSTON, TEXAS 77060


Form C-103 Report of Plugging for your LOWE STATE GAS COM #2 S-36-21-23 API 30-015-25654
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to
indicate that the work has been accomplished and the location is ready for final inspection.


- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in
concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name,
well number and location including quarter/quarter section or unit letter, section, township, range and API
well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been
cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been
leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for
plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and
returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and
approval.


Name


Title


Phil Hawkins
Field Inspector