

S

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410



OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-32570
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. 28924

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	Lease Name or Unit Agreement Name El Presidente State
Name of Operator Nadel and Gussman Permian, L.L.C.	
Address of Operator 601 N. Marienfeld, Suite 508	Well No. #2
Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>24S</u> Range <u>27E</u> NMPM <u>Eddy</u> County	Pool name or Wildcat Black River (Atoka/Morrow)
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run 9-5/8" csg. and set @ 6018'.
Circ. casing & RU Schlumberger. Cement 9-5/8" casing w/1550 sx 50/50 poz lead cmt & 300 sx class C nea. Circ 240 sx to pit.
WOC, cut off csg, install wellhead, NU & test BOP & choke manifold.
Notify NMOCD before cementing.

Time?

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel Martin TITLE Engineering Manager DATE 4/8/03

TYPE OR PRINT NAME Joel Martin TELEPHONE NO. 915/682-4429

(This space for State Use)

APPROVED BY Accepted for record TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 16 2003