Form 3160-5 (August 1999)

1. Type of Well

Name of Ope LYNX PÉT 3a. Address POBOX 1 HOBBS, N

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

MMOCD

<del>RECEIVED</del>

AUG 2 6 2004 OCD:ARTESIA

FORM APPROVED OMB NO. 1004-0135

ber 30, 2000

Expires. Novelile
Lease Serial No.
NINANINARRON

11. County or Parish, and State

EDDY COUNTY, NM

SUNDKY N	OTICES AND REPORTS ON WELLS
Do not use this:	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals

abandoned well. Use form 3160-	o. It indian, Anottee of Trioe Name	
SUBMIT IN TRIPLICATE - Other is	7. If Unit or CA/Agreement, Name and/or No. NMNM111028	
ype of Well ☐ Oil Well ☐ Gas Well ☐ Other		8. Well Name and No. KITTY HAWK FEDERAL 1
	ntact: ANDREA SCOTT E-Mail: lynxpet@leaco.net	9. API Well No. 30-015-32746-00-S1
Address O BOX 1708 OBBS, NM 88241	3b. Phone No. (include area code) Ph: 505.392.6950 Fx: 505.392.7886	10. Field and Pool, or Exploratory SHUGART-MORROW SHUGART-STRAWN

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION		ТҮРЕ О	F ACTION	
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize  Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	□ Production (Start/Resume) □ Reclamation □ Recomplete □ Temporarily Abandon □ Water Disposal	Water Shut-Off Well Integrity Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Propose to recomplete as follows:

1. Kill well w/50 bbls. 2% KCL treated fresh water.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 1 T19S R31E NWSE 1980FSL 1850FEL

- ND tree. NU BOP. Unset packer. Tally tubing out of hole.
- RU Schlumberger. Set CIBP @ 12010'. Cap w/ 35' cement.

Perforate Atoka.

TIH pkr, 1.81" profile nipple, On/Off tool, and tubing. ND BOP. NU tree.

Swab well for evaluation.

14. Thereby certify	For LYNX PETROLEUN	86 verified by the BLM Well Information System  CONSULTANTS INC, sent to the Carlsbad sing by LINDA ASKWIG on 08/23/2004 (04LA0758SE)	
Name (Printed/T	Cyped) LARRY R. SCOTT	Title PRESIDENT	
Signature	(Electronic Submission)	Date 08/20/2004	
	THIS SPACE FOR	FEDERAL OR STATE OFFICE USE	
	EXIS C SWOBODA QL		08/24/2
certify that the applica	al, if any, are attached. Approval of this notice does not ant holds legal or equitable title to those rights in the su the applicant to conduct operations thereon.		
m: 1 10 77 0 0 0 :			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.