OCD-ARTESIA

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APROVED OMB NO. 1004-0135 EXPIRES: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

5 Lease Serial No. NM 012121: BHL NM 036379 Do not use this form for proposals to drill or to re-enter an 6 It Indian Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. 1a. Type of Well ☑ Oil Well Gas Well Other 8 Well Name and No. Cotton Draw Unit 156H Name of Operator **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 3. Address and Telephone No. 30-015-38557 20 N. Broadway. Oklahoma City, Ok 73102-8260 10. Field and Pool, or Exploratory 4. Location of Well (Report location clearly and in accordance with Federal requirements)* Poker Lake South; Delaware 11. County or Parish 200 FNL 660 FEL A 35 T24S R31E State BHL, 200 FSL & 660 FEL 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Drilling ✓ Subsequent Report Casing Repair **New Construction** Recomplete Plug and Abandon Change Plans Temporarily Abandon Operations Final Abandonment Notice 🗌 Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operations (Clearly state s, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposa deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations of the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 3/22/11 - MIRU spud well, Notified Legion w/ BLM. 3/23/11 - TD 17 1/2" hole @ 826'. 3/24/11 - 3/25/11 - RIH w/ 19 jts 13 3/8" 48# H40 STC csg & set @ 846'. RU BJ & lead w/ 530 sx C, 13.5 ppg + 2% CALC2 + 1/8#/sx CF + 4% Gel, Yld 1.74 cf/sx. Tail w/ 250sx C 14.8 ppg, 2% CALCL2 + 1/8#/sx CF + 4% Gel, Yld 1.35 cf/sx. Displ w/ 123 bbls FW. Circ 220 sx. Rlse Ashton rig @ 06:00. 4/15/11 - Commence drlg operations w/ H&P rig. CHC. PT csg to 1200 psi, 30 mins, good. 4/20/11 - 4/22/11 - TD 12 1/4" hole @ 4404'. Notifed BLM. RIH w/ 95 jts 9 5/8" 40# J55 LTC csg & set @ 4404'. RU BJ lead w/ 1225 sx POZ 35:65 C,12.5 ppg, Yld 2.04 cf/sx. Tail w/ 300 sx 60:40 C,13.8 ppg Yld 1.38 cf/sx. Drop cmt plug. displ w/ 330 bbls FW. Held 5 min. Circ 214 sx to surf. WOC. TOC @ 3680'.) Long string por Judy 4/23/11 - NU BOP & test annular 250 psi low land 2500 psi high. Test csg to 1500 psi, 30 mins, good. 5/3/11 - RU loggers & log hole. 5/16/11 - 5/17/11 - TD 8 1/2" hole @ 12,738'. RIH w/166 jts 5 1/2" 17# N80 LTC csg & 121 jts 17# N80 BTC csg & set @ 12,738'. (46 turbolizers every other it 4211-8035') 5/19/11 - RU BJ 1st stage: Lead w/ 278 sx POZ 35:65, Yld 2.01 cf/sx. Tail w/ 2184 sx POZ 50:50, Yld 1.28 cf/sx. DV @ 5894'. 2nd Stage: Lead w/ 343 sx C, Yld 2.88 dv/sx. Tail w/ 130 sx C, Yld 1.37 cf/sx, Test to 3140 psi, good. PBTD @ 12.734'. 5/21/11 - RIse 14. Thereby certify that the foregoing is the and correct

Name Judy A. Barnett X8699 Regulatory Specialist Date 6/21/2011 (This space for Federal or State Office use) Approved by Conditions of approval, if any:

*See Instruction on Reverse Side

within its jurisdiction

Accepted for record NMOCD 3 22 1-2011

RECEIVED JUL 15 2011 NMOCD ARTESIA

