<u>03/23</u> /2005 09:44 FAX 9729		1D WALCHTEON THE		• • •	TOUTH CARDS
oia I	ergy, Miner	als and Natural Reso	urces 🔨		May 27, 2004
5625 N. Prench Dr., Llobbs, NM 88240 District II			WEI.LA	-	
1301 W. Grand Ave., Artesia, NM 88210		RVATION DIVIS		te Type of Lease	
District III 1000 Rio Brezos Rd., Aztoc, NM 87410		outh St. Francis Dr.	S. Haica		tee 🛛
District IV	Santa	Fe, NM 87505		Oil & Gas Lease N	To.
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NO	TICES AND REPORT	S ON WELLS	7. Lease	Name or Unit Ag	reement Name
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPL	OSALS TO DRILL OF TO D	יי שיי אם בזו ומ פה משפאקו	DA	- · · · · · · · · · · · · · · · · · · ·	X 10000
PROPOSALS.)	CATION FOR PERMIT" (F	ORM C-101) FOR SUCH		HAINES	
1. Type of Well: Oil Well	Gas Well 🛛 Otho	<u> </u>	8. Well 1	Number	1
2. Name of Operator	ATDOWNSON OF A	7.6 7	9, OGRI	D Number	
3. Address of Operator	MURCHISON OIL & (AS, INC.	10 7007		5363
-	1100 MIRA VISTA BI	VD., PLANO, TX. 75		náme or Wildcat LOGAN DRAW;	MODDOW
4. Well Location		70.,121.00, 131, 731	77-1078 O11DES.	LOGAN DRAW;	MOKKOW
Unit Letter F	: 1980 feet from t	L MODULE L			
Section 19				eet from theW	
	Townshi	p 17-S Rango www.whether DR, RKB, R	27-E NMPM	1 Cour	xty EDDY
	3302'		i, Cr., eic.)		-
Pit of Below-grade Tank Application	or Clasure 🗌			PRODUCTION AND AND AND AND AND AND AND AND AND AN	
Pit typeDepth to Ground	waterDistance from	nearest frosh water well_	Distance from nea	rest surface water	
Pit Liner Thickness: mil			bbls; Construction Mat	1	
12 Check					
12. CHOOR	white pox ic	Indicate Nature of	nouce, Report of	Other Data	
TEMPORARILY ABANDON FULL OR ALTER CASING COTHER:	MULTIPLE COMPL	. D CASINO	ENCE DRILLING OPI B/CEMENT JOB :	NŞ.∏ PANDA ⊠	
13. Describe proposed or com	pleted operations. (Cle	stly state all pertinent	details, and give perti	nent dates, includi	ng estimated dat
of starting any proposed vor recompletion.	Work). SEE RULE 110	3. For Multiple Compl	etions: Attach wellbo	ore diagram of pro	posed completion
01 2000(\$101011					
Drill 12-1/4" hole to 1500'.	Contacted Jerry Guy w	NMOCD to witness co	ententiob. Ran 9-5/8	" 40 K-55 LT&C	casing as follows
			,	(1111)	-MOTTING OF YOTTO ME
	uide Shoe	1'			
	5/8" 40#/FT K-55 LT& at Collar	C 44'			
	-5/8" 40#/FT K-55 LT&	kC 1459'			
	TOTAL	1505'			
Pump 655 SXS Haliburton Li Bumped plug and floats held Hydrill to 1500 PSI. WOC to	. Circulated 118 SXS t	o reserve pit. WOC 71 hole and drill out shoe	iRS. Change out BC and resume drilling	De Test BAD's	TOT 0002 of
		TEST CASING TO	1000 bel		
		Haw Por 30	min mil		
			MAG		
hereby coutify that the information	a aboralia tendand a	onlare to the base of			
I hereby certify that the information grade tank has been will be constructed to	t tracks become the town	ipiete to the dest of my CD guidelines [], a general	knowledge and belie nermit or an (attached	f. I further certify th	at any pit or below-
# # # # # # # # # # # # # # # # # # #				у апериятия Осту-ар	provea phili 🗀.
SIGNATURE //VUIVUI	1/augush	TTTLEV.P. OP	ERATIONS	DATE	3/16/2005
Type or print name MICHAEL S.	DAUGHERT	E-mail Address	dan ah am 2014-11	_	
For State Use Only		D-man addices: (D	daugherty@jdmii.cox	n Telephone No	. (972) 931-0700
·	ש שברתחחפ ת	NI Y		MAR 9	3 2000
APPROVED BY: FOR	RECORDS O	TITLE		DATE	
Conditions of Approval (if any):	A				
	/1	/ -			

Amended

Submit 3 Copies To Appropriate Dis Office	State	of New Mexico	Form C-103 May 27, 2004
<u>District I</u> 1625 N. French Dr., Hobbs, NM 882	•	ls and Natural Resources	WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 8	OIL CONSER	RVATION DIVISION	30-015-33477
District III 1000 Rio Brazos Rd., Aztec, NM 87	1220 Sou	th St. Francis Dr.	5. Indicate Type of Lease STATE FEE
District IV	Santa	Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NR 87505			
	NOTICES AND REPORTS OF TO DELL OR TO DELL		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE ".	PROPOSALS TO DRILL OR TO DE APPLICATION FOR PERMIT" (FOR	RM C-101) FOR SUCH	HAINES
1. Type of Well: Oil Well	☐ Gas Well ☑ Other		8. Well Number 1
2. Name of Operator	MUDCINCON OU & C	MAR 2 1 2005	9. OGRID Number
3. Address of Operator	MURCHISON OIL & GA	AS, INC. WWW.ARTECH	015363 10. Pool name or Wildcat
1	1100 MIRA VISTA BLV	D., PLANO, TX. 75093-4698	
4. Well Location			
Unit Letter F		e NORTH line and 27 F	1980 feet from the WEST line
Section 19	Township 11. Elevation (Show)	17-S Range 27-E whether DR, RKB, RT, GR, et	NMPM County EDDY
	3302' Gl		-/
Pit or Below-grade Tank Application		D. D.	4
Pit type Depth to Gr Pit Liner Thickness:	oundwaterDistance from n mil Below-Grade Tank: Vo		stance from nearest surface water nstruction Material
		Indicate Nature of Notice	
NOTICE O	DF INTENTION TO: RK ☐ PLUG AND ABANDO	N 🗌 REMEDIAL WO	BSEQUENT REPORT OF: RK
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. P AND A
TEMPORARILY ABANDON PULL OR ALTER CASING	☐ CHANGE PLANS ☐ MULTIPLE COMPL	CASING/CEME	
PULL OR ALTER CASING OTHER:	MULTIPLE COMPL	☐ CASING/CEME	NT JOB
OTHER: 13. Describe proposed or	MULTIPLE COMPL completed operations. (Clear	CASING/CEMEI OTHER: rly state all pertinent details, a	
OTHER: 13. Describe proposed or of starting any propo or recompletion.	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103.	CASING/CEMENT OTHER: rly state all pertinent details, at For Multiple Completions:	NT JOB Indigive pertinent dates, including estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150	multiple completed operations. (Clear sed work). SEE RULE 1103.	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions:	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150	multiple completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ North Guide Shoe 9-5/8" 40#/FT K-55 LT&C	CASING/CEMENT OTHER: rly state all pertinent details, at For Multiple Completions: NMOCD to witness cement join 1' 44'	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150	multiple completed operations. (Clear sed work). SEE RULE 1103.	CASING/CEMENT OTHER: rly state all pertinent details, at For Multiple Completions: NMOCD to witness cement joint of the completion of th	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1 1 Jt 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. 0'. Contacted Jerry Guy w/ N Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar	CASING/CEMENT OTHER: rly state all pertinent details, at For Multiple Completions: NMOCD to witness cement joint of the completion of th	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ N Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Saheld. Circulated 118 SXS to	CASING/CEME CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement job 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele followed reserve pit. WOC 7 HRS. CI	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ M Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Sa held. Circulated 118 SXS to a DC total of 21 HRS. Run in he	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement job 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele followed reserve pit. WOC 7 HRS. Clobe and drill out shoe and resu	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion b. Ran 9-5/8" 40 K-55 LT&C casing as follows b. By 250 SXS Premium Plus + 2% CaCl. nange out BOP's. Test BOP's to 5000 PSI. Test mange drilling formation w/ 8-1/2" bit.
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ Management of Section 1103. Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Sampled. Circulated 118 SXS to 10 C total of 21 HRS. Run in head of the section above is true and complete the section and complete the section above is true and complete the section and	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement job 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele follower reserve pit. WOC 7 HRS. Cl ole and drill out shoe and resu	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion b. Ran 9-5/8" 40 K-55 LT&C casing as follows b. Ran 9-5/8" 40 K-55 LT&C casing as follows as follows by 250 SXS Premium Plus + 2% CaCl. nange out BOP's. Test BOP's to 5000 PSI. Test ame drilling formation w/ 8-1/2" bit.
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ Management of Section 1103. Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Sampled. Circulated 118 SXS to 10 C total of 21 HRS. Run in head of the section above is true and complete the section and complete the section above is true and complete the section and	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement job 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele followed reserve pit. WOC 7 HRS. Clote and drill out shoe and resulted to the best of my knowled.	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion b. Ran 9-5/8" 40 K-55 LT&C casing as follows b. Ran 9-5/8" 40 K-55 LT&C casing as follows as follows by 250 SXS Premium Plus + 2% CaCl. nange out BOP's. Test BOP's to 5000 PSI. Test ame drilling formation w/ 8-1/2" bit.
OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ N Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Sa held. Circulated 118 SXS to DC total of 21 HRS. Run in held. contacted of 21 HRS. Run in held.	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement join 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele followed reserve pit. WOC 7 HRS. Club ole and drill out shoe and resulted to the best of my knowled of guidelines , a general permit TITLE V.P. OPERATIO	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion b. Ran 9-5/8" 40 K-55 LT&C casing as follows b. Ran 9-5/8"
PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ N Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Sa held. Circulated 118 SXS to DC total of 21 HRS. Run in held. contacted of 21 HRS. Run in held.	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement job 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele followed reserve pit. WOC 7 HRS. Clote and drill out shoe and result of the best of my knowled by guidelines , a general permit TITLE V.P. OPERATIO E-mail address: mdaughered	Ind give pertinent dates, including estimated date Attach wellbore diagram of proposed completion b. Ran 9-5/8" 40 K-55 LT&C casing as follows b. Ran 9-5/8"
OTHER: 13. Describe proposed or of starting any propo or recompletion. Drill 12-1/4" hole to 150 1	MULTIPLE COMPL completed operations. (Clear sed work). SEE RULE 1103. O'. Contacted Jerry Guy w/ N Guide Shoe 9-5/8" 40#/FT K-55 LT&C Float Collar 9-5/8" 40#/FT K-55 LT&C TOTAL on Lite Premium + 5 #/SX Sa held. Circulated 118 SXS to DC total of 21 HRS. Run in he mation above is true and comp tedyor floated according to NMOCD LULL S. DAUGHERTY	CASING/CEME OTHER: rly state all pertinent details, a For Multiple Completions: NMOCD to witness cement job 1' 44' 1' 2 1459' 1505' It + .25 #/SX Flocele followed reserve pit. WOC 7 HRS. Clote and drill out shoe and result of the best of my knowled by guidelines , a general permit TITLE V.P. OPERATIO E-mail address: mdaughered	nd give pertinent dates, including estimated date Attach wellbore diagram of proposed completion b. Ran 9-5/8" 40 K-55 LT&C casing as follows b. Ran 9-5/8"