


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brázos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nmlb 1125234220 **274841** **OPERATOR** ☒ Initial Report ☐ Final Report

| | | | |
|-----------------|------------------------------|---------------|---------------|
| Name of Company | ALAMO PERMIAN RESOURCES, LLC | Contact | STEVEN MASTIN |
| Address | 415 W. WALL ST. SUITE 500 | Telephone No. | 432 557 5847 |
| Facility Name | BERRY A 33 | Facility Type | IAJ |

| | | | | | |
|---------------|---------|---------------|---------|---------|--------------|
| Surface Owner | FEDERAL | Mineral Owner | FEDERAL | API No. | 30-015-25154 |
|---------------|---------|---------------|---------|---------|--------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| K | 24 | 17S | 27E | 1650 | S | 2040 | W | EDDY |

Latitude 32.8168411354531

Longitude -104.234151895391

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: OIL & WATER | Volume of Release: EST 18 BBLs (3bbls oil & 15 bbls water) | Volume Recovered: |
| Source of Release: OVERFLOW TANK | Date and Hour of Occurrence: EST JULY 14, 2011 | Date and Hour of Discovery: APPROX AUG 14, 2011 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? JENNIFER VAN CUREN w/ BLM | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Cause of problem: An electrical malfunction caused an injection pump to be down long enough that the overflow tank ran over | | |
| Describe Area Affected and Cleanup Action Taken.* TBD | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <u>Carie Stoker</u> | OIL CONSERVATION DIVISION | |
| Printed Name: CARIE STOKER | Signed By: <u>M. L. Brannon</u> | |
| Title: REGULATORY/ PRODUCTION TECH | Approved by Environmental Specialist: | |
| E-mail Address: cstoker@alamoresources.com | Approval Date: SEP 09 2011 | Expiration Date: |
| Date: 08/29/2011 Phone: 432 664 7659 | Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION | Attached <input type="checkbox"/> |

* Attach Additional Sheets If Necessary

PROPOSAL NOT LATER THAN:

10/9/2011

2RP-881